

→ lathe machine parameter

- Cutting Speed
- feed
- depth of cut

→ lathe machine accessory

- Jaws (three & four)
- lathe dog
- face plate
- flower rest
- Stead rest
- lead ~~rest~~ Center
- half Center.

→ machining time

→ taper operation

- types of taper
- taper angle