

6th day part 4 (9097777 1597)

✓ machine Safety

- ✓ lathe machine * Operation → facing
 - turning
 - drilling
 - threading
 - knurling
 - parting
 - chamfering ----

* Parameter → cutting speed

→ feed

→ depth of cut

* Cutting tool → based on operation

→ based on material

✓ Welding * types of welding - MIG

- TIG

- Spot welding

→ Gas welding

✓ Casting * Pattern → types of Pattern

→ Pattern material

→ Allowance

* Mould → mould material

→ types of mould

* Casting equipment

* Casting Safety tool

* Melting & pouring