

36. In case of unsaturated air

- A. dew point < wet bulb temperature
- B. wet bulb temperature < dry bulb temperature
- C. both (a) and (b)
- D. neither (a) nor (b)

Answer: Option C

Explanation:

No answer description available for this question. [Let us discuss.](#)

[View Answer](#)

[Discuss in Forum](#)

[Workspace](#)

[Report](#)

37. For a binary mixture with low relative volatility,

- A. use steam distillation.
- B. use molecular distillation.
- C. use high pressure distillation.
- D. an azeotrope may be formed during distillation.

Answer: Option D

Explanation:

No answer description available for this question. [Let us discuss.](#)

[View Answer](#)

[Discuss in Forum](#)

[Workspace](#)

[Report](#)

38. Plate efficiency

- A. is a function of the mass transfer between liquid and vapour.
- B. increases due to foaming.
- C. increases due to liquid entrainment.
- D. increases due to weeping and dumping of liquid.

Answer: Option A

Explanation:

No answer description available for this question. [Let us discuss.](#)

[View Answer](#)[Discuss in Forum](#)[Workspace](#)[Report](#)

39. Absorption accompanied by heat evolution results in

- A.** increased capacity of the absorber.
- B.** increase in equilibrium solubility.
- C.** decrease in equilibrium solubility.
- D.** none of these.

Answer: Option **C**

Explanation:

No answer description available for this question. [Let us discuss.](#)

[View Answer](#)[Discuss in Forum](#)[Workspace](#)[Report](#)

40. Even though bubble cap towers are very effective for humidification operation, they are not used commonly in industries, because of the

- A.** high evaporation losses of water.
- B.** high pressure drop of the gas.
- C.** difficulty in its fabrication.
- D.** none of these.

Answer: Option **B**

Explanation: