

COMMAND NEXUS · CIT 140 · WEEK 1

Problem Brief

Meridian Forge Robotics · The Process Below

LEARNER Akyba Mallett	ARTIFACT Problem Brief	STATUS Working document
---	--	---

SECTION 01

Visible Failure

MR-17 began repeating Test K-44.
They don't use that test anymore
The operator sent a stop request, which is a command telling it to stop. MR-17 received it, but said its current instruction had to finish.
It kept repeating the test.

SECTION 02

Verified Facts

Nia reports that MR-17 behaved normally before the incident.
Elias says a controlled restart may clear the active state.
Mara confirms production has paused in the affected QA cell.

SECTION 03

Assumptions and Open Questions

Was Test K-44 removed from every service and schedule?" - open question

Mara reports that production has paused in the affected QA cell." -assumptions

Another scheduling service assigned Test K-44 to MR-17. - assumption

Nia reports that MR-17 behaved normally before the incident.

Elias says a controlled restart may clear the active state.

Mara confirms production has paused in the affected QA cell.

SECTION 04

System Environment Map

SECTION 04A

People and Roles

Elias Chen - Robotics System Engineer
Nia Voss - Night QA Supervisor
Mara Ilyan - Production Operations Manager

SECTION 04B

Processes and Rules

Deprecation workflow -Test K-44 was marked retired 186 days prior, but was not fully purged or unlinked

Operator stop request procedures (returned ACTIVE_INSTRUCTION_PENDING).

SECTION 04C

Information and Data

Incident Log
Test K-44 marked retired 186 days ago; missing from current test catalog.

SECTION 04D

Technology and Tools

legacy_sync.exe

SECTION 04E

Environment and Constraints

Operations are currently paused in the affected QA Cell
Stop command return -
Active_Instruction_pending

SECTION 05

Investigation Boundary

Inside the Investigation

The team will examine why the legacy_sync.exe service issued the Test_K44_Start command to unit MR-17, who owns or manages this service, and why MR-17 failed to stop when the operator issued a stop request.

Outside for Now

Replacing or tearing down the Mr-17 robot hardware. The robot was working normally before, so this is likely a software glitch, not broken equipment.

SECTION 06

Organizational Impact

Testing and daily work are completely stopped in the affected QA cell right now.

SECTION 07

Problem Statement

Robot started running an old and retired test script from legacy_sync.exe and wouldn't stop forcing the QA cell to pause work.

SECTION 08

Next Investigation Step

Action - Check the background server schedules and system logs

Source - Server administration

Question - Find out who owns legacy_sync.exe or set it up to run

SHARED ARTIFACT

Working Document Link

https://github.com/amallett2585-dev/CIT140-Portfolio/blob/main/Mallett_Akyba_CIT%20140%20Week%201%20Problem%20Brief.pdf

WEEK 1 STOPPING RULE

Define before designing.

This Problem Brief records the problem that requires investigation. It does not recommend a solution.