

Total Monitored Devices

36

Fleet Avg Temp

25

Peak Thermal Load

27

Healthy Assets

28

Unhealthy Assets

8

Timeline Filter

30-04-202109-05-2021

Clear All Filters

Device Type



All

Health Status

All

Factory Location

All



Granular Asset Health & Location Matrix

Column1.location.country	Device Count	Avg Temp	Status
china	9	24.99	healthy
germany	9	24.99	healthy
japan	18	24.99	healthy
Total	36	24.99	healthy

Executive Insights & Action Plan

⚠

The Finding (Critical Concentration):

Downtime is not evenly distributed across the fleet. Over 90% of all recorded fault events are isolated to just two asset classes: **Laser Welder** (48 events) and **Laser Cutter** (43 events).

🔍

The Root Cause (Thermal Lock):

Telemetry indicates these specific heavy-load machines frequently hit the hard-coded peak thermal threshold of 27°C, which triggers an automated 'Unhealthy' status and halts production.

•

🔧 Actionable Solution (Targeted Maintenance):

a. Divert immediate maintenance bandwidth from healthy assets (like CNC & Conveyor Belts) directly to Laser machinery.

b. Inspect and upgrade the secondary cooling systems / exhausts specifically for Laser Welders in the affected factories.