NCR\_1313 no hairpin | 4 basepaired positions in spacer 0 fM rate: 5.96 100 fM rate: 15.4 4500 p = 9.26e - 444000 activator RFU noActivator 100fM 3500 3000 2500 0 30 60 90 120

time (min)