NCR\_1317 no hairpin | 4 basepaired positions in spacer 6000 0 fM rate: 5.16 100 fM rate: 28.2 p = 2.08e - 575000 activator noActivator 100fM 3000 2000 60 0 30 90 120 time (min)