NCR\_1346 no hairpin | 16 basepaired positions in spacer 20000 -0 fM rate: 1.88 100 fM rate: 131 p = 2.99e - 22515000 activator noActivator 100fM 10000 -5000 -30 60 0 90 120 time (min)