

5.7.5. Commissioning Fallback Mechanism

Commissioning using any of the methods described above can potentially fail for a number of reasons. In some cases this will be a transient failure (e.g., due to wireless interference), while in other cases failure will be systematic (e.g., a mismatch in capabilities of the Commissioner and the Commissionee).

Especially for the latter cases, a fallback mechanism is defined which allows the Commissioner to direct the user to a manufacturer-provided mechanism where the user can be guided towards resolution of the issues since the manufacturer typically has more knowledge about the specific device than the commissioner.

Examples of means that could be employed to attempt to resolve the issues:

- The [Section 11.23.6.14, “CommissioningFallbackUrl”](#) can lead to a web page listing suggestions to resolve the failure (e.g., "restart the device to start another commissioning attempt" which helps in case the 15 minute announcement interval since power-on had expired before commissioning was attempted)
- The [Section 11.23.6.14, “CommissioningFallbackUrl”](#) can lead to a manufacturer-provided mechanism to get the device on the IP-bearing network (which can then be followed by "[commissioning while already on IP-network](#)").

5.7.5.1. Commissioning Fallback flow for Device Manufacturers

For cases where commissioning failure can be anticipated (such as devices which rely on commissioning via a technology which is not mandatory for Commissioners e.g. supporting only commissioning via [Wi-Fi Public Action Frame](#)), the [Section 11.23.6.14, “CommissioningFallbackUrl”](#) and [Section 11.23.6.7, “DiscoveryCapabilitiesBitmask”](#) fields in the [DeviceModel](#) schema in the DCL SHALL be populated. For the [Section 5.1.4, “Manual Pairing Code”](#) for such a product, the [Encoding Method with Vendor and Product ID’s included](#) SHALL be used so the Commissioner has access to the VendorID and ProductID for DCL-lookup of the URL.

For other cases, this field MAY be populated to provide a manufacturer-provided mechanism in case commissioning fails for any (other) reason.

5.7.5.2. Commissioning Fallback flow for Commissioners

When a Commissioner encounters a situation where the commissioning fails systematically (e.g., due to a mismatch in capabilities of the Commissioner and the Commissionee), and it has no other means to guide the user to resolution of the issues, it SHALL use the [Section 11.23.6.14, “CommissioningFallbackUrl”](#) (when provided) in the [DeviceModel](#) schema in the DCL to guide the user to the manufacturer-provided means towards resolution of the commissioning issues.

- In cases where using this URL is technically impossible (e.g. a headless commissioner, or the lack of internet access) or when the Commissioner is performing offline mode commissioning, the Commissioner SHOULD inform the user of the assumed reason for commissioning failure, and MAY provide additional advice on how this could potentially be resolved.

When a Commissioner encounters a situation where the commissioning failure is transient, the Commissioner MAY try again; it also MAY use the [Section 11.23.6.14, “CommissioningFallbackUrl”](#)