

Reference	Reference Location/URL	Description
[RFC 3986]	https://www.rfc-editor.org/rfc/rfc3986	Uniform Resource Identifier (URI)
[WakeOnLAN]	https://www.amd.com/system/files/TechDocs/20213.pdf	Wake on LAN Magic Packet specification

Provisional

Per [Alliance-PNP], when a specification is completed there may be sections of specification text (or smaller pieces of a section) that are not certifiable at this stage. These sections (or smaller pieces of a section) are marked as provisional prior to publishing the specification. This specification uses well-defined notation to mark Provisional Conformance (see [MatterCore], Section 7.3) or notes a section of text with the term "provisional".

List of Provisional Items

The following is a list of provisional items:

- Support for the Frequency feature of the [Level Control cluster](#) is provisional.
- Support for InflowError, DrainError, TempTooLow, TempTooHigh, and WaterLevelError alarms in [Dishwasher Alarm Cluster](#) is provisional.
- Support for [Energy Preference Cluster](#) is provisional.
- Support for [Content Control Cluster](#) is provisional.
- Support for PowerInWatts feature of the [Microwave Oven Control cluster](#) is provisional