

ID	Name	Type	Constraint	Quality	Fallback	Access	Conformance
0x0001	MinMeasuredValue	single	all	X		R V	MEA
0x0002	MaxMeasuredValue	single	min Min-Measured-Value	X		R V	MEA
0x0003	PeakMeasuredValue	single	MinMeasuredValue to MaxMeasuredValue	P X		R V	PEA
0x0004	PeakMeasuredValueWindow	elapsed-s	max 604800	P		R V	PEA
0x0005	AverageMeasuredValue	single	MinMeasuredValue to MaxMeasuredValue	P X		R V	AVG
0x0006	AverageMeasuredValueWindow	elapsed-s	max 604800	P		R V	AVG
0x0007	Uncertainty	single	MS		MS	R V	[MEA]
0x0008	MeasurementUnit	MeasurementUnitEnum		F		R V	MEA
0x0009	MeasurementMedium	MeasurementMediumEnum		F		R V	M
0x000A	LevelValue	LevelValueEnum				R V	LEV

2.10.6.1. MeasuredValue Attribute

This attribute SHALL represent the most recent measurement as a single-precision floating-point number. MeasuredValue's unit is represented by MeasurementUnit.

A value of null indicates that the measurement is unknown or outside the valid range.

MinMeasuredValue and MaxMeasuredValue define the valid range for MeasuredValue.