

3.2.8.22.5. ColorTemperatureMaximumMireds Field

This field SHALL indicate an upper bound on the ColorTemperatureMireds attribute ($\equiv$ a lower bound on the color temperature in kelvins) for the current step operation such that:

$$\text{ColorTemperatureMireds} \leq \text{ColorTemperatureMaximumMireds field} \leq \text{ColorTempPhysicalMaxMireds}$$

As such if the step operation takes the ColorTemperatureMireds attribute towards the value of the ColorTemperatureMaximumMireds field it SHALL be clipped so that the above invariant is satisfied. If the ColorTemperatureMaximumMireds field is set to 0, ColorTempPhysicalMaxMireds SHALL be used as the upper bound for the ColorTemperatureMireds attribute.

3.2.8.22.6. OptionsMask and OptionsOverride Fields

These fields SHALL be processed according to section [Use of the OptionsMask and OptionsOverride Fields](#).

3.2.8.22.7. Effect on Receipt

On receipt of this command, if the StepSize field has a value of zero, the command has no effect and a response SHALL be returned with the status code set to INVALID_COMMAND.

Otherwise, a device SHALL set both the ColorMode and EnhancedColorMode attributes to 2 (ColorTemperatureMireds). The device SHALL then move from its current color temperature in an up or down direction by one step, as detailed in the table.

StepMode	Action on Receipt
Up	Increase the ColorTemperatureMireds attribute ($\equiv$ decrease the color temperature in kelvins) by one step. If the ColorTemperatureMireds attribute reaches the maximum allowed for the device (via either the ColorTemperatureMaximumMireds field or the ColorTempPhysicalMaxMireds attribute), the step operation SHALL be stopped.
Down	Decrease the ColorTemperatureMireds attribute ($\equiv$ increase the color temperature in kelvins) by one step. If the ColorTemperatureMireds attribute reaches the minimum allowed for the device (via either the ColorTemperatureMinimumMireds field or the ColorTempPhysicalMinimumMireds attribute), the step operation SHALL be stopped.