

5.2.10.42.5. Effect on Receipt

1. If the lock already has an Aliro Reader configuration defined, (i.e. the AliroReaderVerificationKey attribute is not null), the response SHALL be INVALID_IN_STATE.

NOTE

This avoids accidentally overwriting values that were just set by a different administrator. If overwriting those is desired, they should be explicitly cleared with the [ClearAliroReaderConfig](#) command.

2. Otherwise:

- a. The door lock server SHALL save the SigningKey internally.
- b. The AliroReaderVerificationKey attribute SHALL be set to the value of VerificationKey.
- c. The AliroReaderGroupIdentifier attribute SHALL be set to the value of GroupIdentifier.
- d. If the AliroBLEUWB feature is supported, the AliroGroupResolvingKey attribute SHALL be set to the value of GroupResolvingKey.
- e. The response SHALL be SUCCESS.

5.2.10.43. ClearAliroReaderConfig Command

This command allows clearing an existing Aliro Reader configuration for the lock.

Administrators SHALL NOT clear an Aliro Reader configuration without explicit user permission.

NOTE

Using this command will revoke the ability of all existing Aliro user devices that have the old verification key to interact with the lock. This effect is not restricted to a single fabric or otherwise scoped in any way.

5.2.10.43.1. Effect on Receipt

On receipt of this command:

1. The door lock server SHALL clear out the stored SigningKey.
2. The AliroReaderVerificationKey and AliroReaderGroupIdentifier attributes SHALL be set to null.
3. If the AliroBLEUWB feature is supported, the AliroGroupResolvingKey attribute SHALL be set to null.

5.2.11. Events

This cluster SHALL support these events:

ID	Name	Priority	Quality	Access	Conformance
0x00	DoorLock-Alarm	CRITICAL		V	M
0x01	DoorState-Change	desc		V	DPS