

- 1 = the latch can be latched via remote control (e.g., electronic or remote actuation).

5.4.6.7.2. RemoteUnlatching Bit

This bit SHALL indicate whether the latch supports remote unlatching or not:

- 0 = the latch can only be unlatched through manual, physical operation.
- 1 = the latch can be unlatched via remote control (e.g., electronic or remote actuation).

5.4.7. Attributes

ID	Name	Type	Constraint	Quality	Fallback	Access	Conformance
0x0000	Count-downTime	elapsed-s	max 259200	Q X	null	R V	[PS & !IS]
0x0001	MainState	MainStateEnum	all			R V	M
0x0002	CurrentErrorList	list[ClosureErrorEnum]	max 10[all]			R V	M
0x0003	OverallCurrentState	OverallCurrentStateStruct	all	X	null	R V	M
0x0004	OverallTargetState	OverallTargetStateStruct	all	X	null	R V	M
0x0005	LatchControlModes	LatchControlModesBitmap	all	F		R V	LT

5.4.7.1. CountdownTime Attribute

This attribute SHALL indicate the estimated time left before the operation is completed, in seconds.

A value of 0 (zero) means that the operation has completed.

A value of null indicates that there is no time currently defined until operation completion. This MAY happen because the completion time is unknown.

Changes to this attribute SHALL only be marked as reportable in the following cases:

- If the tracked operation has changed due to a change in the MainState attribute, or
- When it changes from 0 to any other value and vice versa, or
- When it changes from null to any other value and vice versa, or
- When it increases, or