

Conformance	Feature	Meaning
X	false	This is used in a device type that overrides cluster specification conformance, which means the conformance expression is false, and the feature is unsupported (false).
P	false	This means the conformance expression is false, and the feature is provisional and unsupported.
<i>false mandatory expression</i>	false	Conformance expressions are used to define more complex feature dependencies. A list of expressions evaluates to a single expression. Choice options only support optional expressions.
<i>false optional expression</i>	false	
<i>true mandatory expression</i>	true	
<i>true optional expression</i>	<i>implementation</i>	

- If the feature indicator (bit) is unsupported, then the feature indicator SHALL be false and the feature SHALL be unsupported (false).
- Otherwise, if the conformance expression evaluates to false, then the feature indicator SHALL be false and the feature SHALL be unsupported (false).
- Otherwise, if the conformance expression evaluates to mandatory, then the feature indicator and feature support SHALL be the value of the conformance expression.
- Otherwise:
 - the feature support (true or false) SHALL be the value of the feature indicator (bit) as implemented.
 - If the conformance expression evaluates to a [choice conformance](#), then the indicators for the choice set SHALL also conform to the choice parameters.

7.4. Element

An element of the data model is a data construct that supports an instance of data. Listed below are the elements of the data model.

First order elements

fabric, node, endpoint, cluster

Cluster first order elements

command, event, attribute

Nested elements

command field, event field, struct field