

Conformance

- Any attribute that is "M" is part of the base mandatory feature set. "O" is purely optional.
- To support the Axis *feature* any attribute with "AX" conformance must be supported (see Data Model).
- To support the Wobble feature any attribute with WBL conformance must be supported (see Data Model).
- "AX | WBL" means either feature mandates this attribute. If neither are true, then the attribute is not allowed.
- "AX & WBL" would require both features supported to mandate.
- "[PAT]" means optional for Pattern feature.
- "P, O" means provisional otherwise optional (after it's no longer provisional).
- The name of another attribute in the conformance column means the attribute is mandatory if the other attribute is supported. Conformance based on the presence of another attribute can be made optional by using []. Conformance MAY be set using any element in the same table.

10.4.1.7.1. Run Attribute

This attribute SHALL indicate if the disco ball is operating. If the Run attribute is 0, then the Speed, Rotate and WobbleSpeed attributes SHALL be 0.

10.4.1.7.2. Rotate Attribute

This attribute SHALL indicate the direction of rotation either clockwise or counterclockwise.

10.4.1.7.3. Speed Attribute

This attribute SHALL indicate the speed of the disco ball in revolutions per minute.

10.4.1.7.4. Axis Attribute

This attribute SHALL indicate the tilt of the axis of the disco ball, in degrees.

10.4.1.7.5. WobbleSpeed Attribute

This attribute SHALL indicate the speed of the wobble rotation in revolutions per minute.

10.4.1.7.6. Pattern Attribute

This attribute SHALL contain an ordered list of pattern entries. This list of patterns SHALL be used to operate the disco ball when the Pattern Request command is invoked.

10.4.1.7.7. Name Attribute

This attribute SHALL indicate a display name.