

11.18.6.15. SignVIDVerificationRequest Command

This command is used to authenticate the fabric associated with the FabricIndex.

This command SHALL be used to request that the server authenticate the fabric associated with the FabricIndex given by generating the response described in [Section 6.4.10, “Fabric Table Vendor ID Verification Procedure”](#).

ID	Name	Type	Constraint	Quality	Fallback	Conformance
0	FabricIndex	fabric-idx	1 to 254			M
1	ClientChallenge	octstr	32			M

The FabricIndex field SHALL contain the fabric index being targeted by the request.

The ClientChallenge field SHALL contain a client-provided random challenge to be used during the signature procedure.

Effect on Receipt

If the FabricIndex field contains a fabric index which does not have an associated entry in the [Fabrics](#) attribute, then the command SHALL fail with a status code of CONSTRAINT_ERROR.

Otherwise, if no other errors have occurred, the command SHALL generate a [SignVIDVerificationResponse](#).

11.18.6.16. SignVIDVerificationResponse Command

This command is used to report the results of the SignVIDVerificationRequest command. This command SHALL contain the response of the [SignVIDVerificationRequest](#), computed as described below.

ID	Name	Type	Constraint	Quality	Fallback	Conformance
0	FabricIndex	fabric-idx	1 to 254			M
1	FabricBindingVersion	uint8	1 to 255			M
2	Signature	octstr	min 1			M

The FabricIndex field SHALL contain the same value of **FabricIndex** as the value from the associated [SignVIDVerificationRequest](#).

The FabricBindingVersion field SHALL contain value 0x01 for version 1.0 of the Matter [Cryptographic Primitives](#).

The Signature field SHALL contain the octet string result of **CryptoSign(noc_private_key, vendor_id_verification_tbs)**: