

Handling of SoftwareVersion and ImageURI fields SHALL follow these rules:

- If the SoftwareVersion field matches the version indicated in the header of a previously downloaded OTA Software Image, one of two cases applies:
 1. Image was fully downloaded and verified: the OTA Requestor SHOULD skip the transfer step (see [Section 11.20.3.5, “Transfer of OTA Software Update images”](#)), and move directly to the apply step (see [Section 11.20.3.6, “Applying a software update”](#)).
 2. Image was partially downloaded: the OTA Requestor SHOULD attempt to continue the transfer from where it left off, if it is capable, otherwise it SHALL start the transfer anew. See [Section 11.20.3.5, “Transfer of OTA Software Update images”](#) for a description of complete and restarted downloads.
- If the SoftwareVersion field indicates a newer (numerically higher) version than the version currently installed on the OTA Requestor, the OTA Requestor SHOULD proceed with OTA Image Transfer (see [Section 11.20.3.5, “Transfer of OTA Software Update images”](#)), after awaiting at least the delay stated by the [DelayedActionTime](#) field, if present.
- If the SoftwareVersion field indicates the same or an older (numerically lower) version, or if the ImageURI field somehow contains information which cannot be used by the OTA Requestor, then the OTA Requestor SHALL go back to awaiting its next OTA Software Update query opportunity, following the rules previously stated in [Section 11.20.3.2, “Querying the OTA Provider”](#). In that case, the OTA Requestor MAY attempt to select a different OTA Provider according to [Section 11.20.3.1, “Determining the OTA Provider to query”](#), which MAY cause the OTA Requestor to immediately try another query, but to a different OTA Provider, thus not violating daily allowance of a given OTA Requestor towards a given OTA Provider.

Handling Busy value in Status field

The Busy status indicates that the OTA Provider is busy for any reason and that it can only provide a definite answer at a later time. This MAY be because the OTA Provider is currently determining whether an update is available for the OTA Requestor that made the query. An OTA Requestor SHOULD attempt to query the same OTA Provider again later at least once more if a Busy response is obtained, rather than querying a different OTA Provider in its list, so that the OTA Provider that replied Busy could have had resources available to determine availability.

After a Busy status, the OTA Requestor SHALL NOT re-query the OTA Provider which was the subject of the command sooner than the longest of either:

- 2 minutes (120 seconds) from the last [QueryImage](#) command;
- the delay stated by the [DelayedActionTime](#) field.

Note that if a Node loses its timekeeping state due to events such as power loss or restart, the above timing constraint MAY be ignored, however, the previously stated overriding constraint of a minimum delay of 120 seconds between queries to any single OTA Provider by a given OTA Requestor has to be respected.

Handling NotAvailable value in Status field

The NotAvailable status indicates that there is definitely no update currently available from the queried OTA Provider.