

update.

DelayedOnApply Value

This value SHALL indicate a Node waiting because it received a prior [ApplyUpdateResponse](#) with an [Action](#) field set to AwaitNextAction.

RollingBack Value

This value SHALL indicate a Node in the process of recovering to a previous version from a new version that was applied, but that could not remain in force, for reasons such as invalid data detected on boot, or significant runtime issues such as reboot loops. Eventually, the next state seen SHOULD be Unknown or Idle.

DelayedOnConsent Value

This value SHALL indicate a Node is capable of [obtaining user consent](#) through its own means, but is currently awaiting that consent after having determined from a prior [QueryImageResponse](#) that an update was available.

ChangeReasonEnum Type

The ChangeReasonEnum Data Type is derived from [enum8](#).

Value	Name	Summary	Conformance
0	Unknown	The reason for a state change is unknown.	M
1	Success	The reason for a state change is the success of a prior operation.	M
2	Failure	The reason for a state change is the failure of a prior operation.	M
3	TimeOut	The reason for a state change is a time-out.	M
4	DelayByProvider	The reason for a state change is a request by the OTA Provider to wait.	O

Unknown Value

This value SHALL indicate that the reason for a state change is unknown.

Success Value

This value SHALL indicate that the reason for a state change is the success of a prior operation.