

attempted commands until successful.

The RESOURCE_EXHAUSTED error MAY be used by the Datastore to indicate that a storage capacity limit of the Datastore has been reached and SHALL notify the user of this condition using proprietary means outside of this specification (ex. email, screen-based notification, etc.), and SHALL provide a means for the user to purge information pertaining to unused Nodes.

11.24.4.1. Adding a Node to the Joint Fabric

During commissioning of a Node onto a Joint fabric, the Fabric Administrator performing the commissioning first populates the Datastore in order to ensure the new Node can be discovered by any client on the fabric for which the user has granted access. Specifically, before completing the commissioning process, the Commissioner SHALL invoke the [AddPendingNode](#) command in order to add a node entry to the Datastore (which will be marked with “pending” status since commissioning of the device has not yet completed), and follow the rules defined in [Section 11.24.4.9, “Adding/Removing access privileges for a Controller”](#), to ensure access privileges are managed consistently across the Joint Fabric. After completion of commissioning and associated configuration, the Commissioner SHALL invoke the [RefreshNode](#) command in order to indicate completion of commissioning and to cause the Datastore to update the Node Information Entry with state read from the Node and mark the entry as “committed”. By performing this work in two steps (first pending status, then committed status), the design can prevent error scenarios where a node is brought onto a fabric without appearing in the Datastore.

Commissioning Flow - Datastore Impact

1. Regular Flow: Commissioner obtains Onboarding Payload, discovers device, completes PASE portion of commissioning.
2. Datastore Step: Commissioner SHALL add a Node Information Entry to the Datastore (see [Section 11.24.7.10, “AddPendingNode Command”](#)).
3. Regular Flow: Commissioner finalizes commissioning via CASE.

If the finalize commissioning step fails, the Commissioner removes the pending node from the Datastore (see [Section 11.24.7.13, “RemoveNode Command”](#)).

If the finalize commissioning step succeeds, the Commissioner SHALL indicate completion by calling the [RefreshNode](#) command.

11.24.4.2. Removing a Node from the Joint Fabric

When removing a Node from the [Joint Fabric](#) the following steps SHALL be followed:

1. The [Joint Fabric](#) Administrator SHALL first remove access privileges (see [Section 11.24.4.9, “Adding/Removing access privileges for a Controller”](#)) for the Node.
2. The Node Information Entry SHALL be removed from the Joint Fabric Datastore using the [RemoveNode](#) command.

11.24.4.3. Pending Data Cleanup

The Datastore SHALL periodically review its data in a [Pending](#) and [PendingDeletion](#) state and