

- a. Another Node which is an Administrator in Ecosystem B instructs the Ecosystem B Administrator, over a [CASE](#) session inside Fabric B, to go into [Section 11.25.7.5, “OpenJointCommissioningWindow”](#)
 - b. Ecosystem B Administrator puts itself in commissionable mode using implementation specific means for calling [Section 11.25.7.5, “OpenJointCommissioningWindow”](#)
2. A new **RANDOM** passcode SHALL be computed and [Section 11.25.7.5, “OpenJointCommissioningWindow”](#) SHALL be called using the corresponding **PAKE** passcode verifier. The new passcode and the discriminator SHALL be presented to Ecosystem A Commissioner using the same rules described by ECM in [Section 5.6.3.1, “Presentation of Onboarding Payload for ECM”](#).
3. On Ecosystem A side, User SHALL be made aware that it has the option of using the [Section 5.1, “Onboarding Payload”](#) in order to start the JCM steps. Once this option is selected, Ecosystem A Commissioner SHALL start execution of the steps outlined in [Figure 45, “Commissioning flow diagram”](#) with Ecosystem B Administrator.
 - a. Commissioning steps proceed through the successful end of Device Attestation Procedure (that would be [Step 10](#)), with standard error handling behavior unchanged.
4. A new step is introduced for verifying trust against Ecosystem B Administrator:
 - a. Ecosystem A Commissioner SHALL search all endpoints' Descriptor cluster of Ecosystem B Administrator for the Joint Fabric Administrator device type, which requires the [Joint Fabric Administrator](#) cluster.
 - i. if **Joint Fabric Administrator** cluster is not found, process SHALL be terminated and the User SHALL be informed that Ecosystem B lacks the expected functionality
 - ii. otherwise the endpoint that contains the [Joint Fabric Administrator](#) cluster SHALL be saved as **JointEndPointB**
 - b. Ecosystem A Commissioner SHALL check that the NOC used by the Fabric indicated by the **AdministratorFabricIndex** of the **Joint Fabric Administrator** Cluster on **JointEndPointB** contains an Administrator CAT.
 - i. if verification fails, process SHALL be terminated and the User SHALL be informed that Ecosystem B Administrator is not trusted
 - c. Ecosystem A Commissioner SHALL execute [Section 6.4.10, “Fabric Table Vendor ID Verification Procedure”](#) against the Fabric indicated by the **AdministratorFabricIndex** of the **Joint Fabric Administrator** Cluster on **JointEndPointB** (i.e. [Section 7.13.6, “FabricIndex”](#) corresponding to Fabric B)
 - i. if verification fails, process SHALL be terminated and the User SHALL be informed that Ecosystem B Administrator is not trusted
 - d. On Ecosystem A side, User SHALL be asked if they agree to onboard the Fabric indicated by **AdministratorFabricIndex**. At least the name associated with the **VendorID** of the onboarded Fabric SHALL be presented to the User.
 - e. Ecosystem A Commissioner SHALL save the **SubjectPublicKey** of the ICAC belonging to the Fabric indicated by **AdministratorFabricIndex** as **TrustedIcacPublicKeyB**
5. [Figure 45, “Commissioning flow diagram”](#) SHALL continue with the original steps between [11 \(CSRRequest\)](#) and [19 \(CASE\)](#):