

ID	Name	Type	Constraint	Quality	Fallback	Access	Conformance
1	RangeMax	int64	-2^{62} to 2^{62}				M
2	PercentMax	percent100ths	all				O.a+
3	PercentMin	percent100ths	max PercentTypical				[PercentMax]
4	PercentTypical	percent100ths	PercentMin to PercentMax				[PercentMin]
5	FixedMax	uint64	max ($2^{62} - 1$)				O.a+
6	FixedMin	uint64	max FixedMax				[FixedMax]
7	FixedTypical	uint64	FixedMin to FixedMax				[FixedMin]

- If both **PercentMax** and **FixedMax** are indicated, then for a given true value in the range between **RangeMin** and **RangeMax**,
 - the reported value SHALL be less than or equal to the sum of the true value, **FixedMax** and **PercentMax** percent of the true value.
 - the reported value SHALL be greater than or equal to the true value minus the sum of **FixedMax** and **PercentMax** percent of the true value.
- If only **PercentMax** is indicated, then for a given true value in the range between **RangeMin** and **RangeMax**,
 - the reported value SHALL be less than or equal to the sum of the true value and **PercentMax** percent of the true value.
 - the reported value SHALL be greater than or equal to the true value minus **PercentMax** percent of the true value.
- If only **FixedMax** is indicated, then for a given true value in the range between **RangeMin** and **RangeMax**,
 - the reported value SHALL be less than or equal to the sum of the true value and **FixedMax**.
 - the reported value SHALL be greater than or equal to the true value minus **FixedMax**.

2.1.3.2.1. RangeMin Field

This field SHALL indicate the minimum measurement value for the specified level of accuracy.

The value of this field SHALL be greater than or equal to the value of the **MinMeasuredValue** field on the encompassing **MeasurementAccuracyStruct**.