

ID	Name	Type	Con- strai nt	Qual ity	Fall- back	Acce ss	Conformance
0x0030	PhysicalContactOccupiedToUnoccupiedDelay	uint16	all	N	0	RW VM	[HoldTime & PHY], D
0x0031	PhysicalContactUnoccupiedToOccupiedDelay	uint16	all	N	0	RW VM	HoldTime & PHY & PhysicalContactUnoccupiedToOccupiedThreshold, [HoldTime & PHY], D
0x0032	PhysicalContactUnoccupiedToOccupiedThreshold	uint8	1 to 254	N	1	RW VM	HoldTime & PHY & PhysicalContactUnoccupiedToOccupiedDelay, [HoldTime & PHY], D

2.7.6.1. Occupancy Attribute

This attribute SHALL indicate the sensed (processed) status of occupancy. For compatibility reasons this is expressed as a bitmap where the status is indicated in bit 0: a value of 1 means occupied, and 0 means unoccupied, with the other bits set to 0; this can be considered equivalent to a boolean.

2.7.6.2. OccupancySensorType and OccupancySensorTypeBitmap Attributes

These attributes SHALL indicate the type of sensor. In ClusterRevision ≤ 4 , these were used to specify the type of the occupancy sensor using a bitmap. For ClusterRevision ≥ 5 , the server SHALL indicate the type of sensor using the feature flags, and the server SHALL provide these attributes for the backward compatibility with clients implementing a cluster revision ≤ 4 , using the mapping according to the following table. Also see [Backward Compatibility section](#).

Feature Flag Value			Value of Occu- pancySen- sorTypeBitmap	Value of Occu- pancySensorType
PIR	US	PHY		
0	0	0	PIR *	PIR *
1	0	0	PIR	PIR
0	1	0	Ultrasonic	Ultrasonic
1	1	0	PIR + Ultrasonic	PIRAndUltrasonic
0	0	1	PhysicalContact	PhysicalContact
1	0	1	PhysicalContact + PIR	PIR **
0	1	1	PhysicalContact + Ultrasonic	Ultrasonic **