

2.10.6.2. MinMeasuredValue Attribute

This attribute SHALL represent the minimum value of MeasuredValue that is capable of being measured. A MinMeasuredValue of null indicates that the MinMeasuredValue is not defined.

2.10.6.3. MaxMeasuredValue Attribute

This attribute SHALL represent the maximum value of MeasuredValue that is capable of being measured. A MaxMeasuredValue of null indicates that the MaxMeasuredValue is not defined.

2.10.6.4. PeakMeasuredValue Attribute

This attribute SHALL represent the maximum value of MeasuredValue that has been measured during the [PeakMeasuredValueWindow](#). If this attribute is provided, the PeakMeasuredValueWindow attribute SHALL also be provided.

2.10.6.5. PeakMeasuredValueWindow Attribute

This attribute SHALL represent the window of time used for determining the PeakMeasuredValue. The value is in seconds.

2.10.6.6. AverageMeasuredValue Attribute

This attribute SHALL represent the average value of MeasuredValue that has been measured during the [AverageMeasuredValueWindow](#). If this attribute is provided, the AverageMeasuredValueWindow attribute SHALL also be provided.

2.10.6.7. AverageMeasuredValueWindow Attribute

This attribute SHALL represent the window of time used for determining the AverageMeasuredValue. The value is in seconds.

2.10.6.8. Uncertainty Attribute

This attribute SHALL represent the range of error or deviation that can be found in MeasuredValue and PeakMeasuredValue. This is considered a +/- value and should be considered to be in MeasurementUnit.

2.10.6.9. MeasurementUnit Attribute

This attribute SHALL represent the unit of MeasuredValue. See [MeasurementUnitEnum](#).

2.10.6.10. MeasurementMedium Attribute

This attribute SHALL represent the medium in which MeasuredValue or LevelValue is being measured. See [MeasurementMediumEnum](#).

2.10.6.11. LevelValue Attribute

This attribute SHALL represent the level of the substance detected. See [LevelValueEnum](#).