

The value of this field SHALL be less than or equal to the value of the [MaxMeasuredValue](#) field on the encompassing [MeasurementAccuracyStruct](#).

2.12.5.1.1.2. RangeMax Field

This field SHALL indicate the maximum measurement value for the specified level of accuracy.

The value of this field SHALL be greater than the value of the [RangeMin](#) field.

The value of this field SHALL be greater than or equal to the value of the [MinMeasuredValue](#) field on the encompassing [MeasurementAccuracyStruct](#).

The value of this field SHALL be less than or equal to the value of the [MaxMeasuredValue](#) field on the encompassing [MeasurementAccuracyStruct](#).

2.12.5.1.1.3. PercentMax Field

This field SHALL indicate the maximum +/- percentage accuracy for the associated measurement.

2.12.5.1.1.4. PercentMin Field

This field SHALL indicate the minimum +/- percentage accuracy for the associated measurement.

2.12.5.1.1.5. PercentTypical Field

This field SHALL indicate the typical +/- percentage accuracy for the associated measurement.

2.12.5.1.1.6. FixedMax Field

This field SHALL indicate the maximum +/- fixed accuracy for the associated measurement, in the unit indicated by [MeasurementType](#).

2.12.5.1.1.7. FixedMin Field

This field SHALL indicate the minimum +/- fixed accuracy for the associated measurement, in the unit indicated by [MeasurementType](#).

2.12.5.1.1.8. FixedTypical Field

This field SHALL indicate the typical +/- fixed accuracy for the associated measurement, in the unit indicated by [MeasurementType](#).

2.12.5.1.2. MeasurementAccuracyStruct Type

This struct represents the set of accuracy ranges for a given measurement, the maximum and minimum values for the measurement, and whether the measurement is directly measured or just estimated from other information.