

2.15.3. Cluster ID

ID	Name
0x0430	Soil Measurement

2.15.4. Attributes

ID	Name	Type	Constraint	Quality	Fallback	Access	Conformance
0x0000	SoilMoistureMeasurementLimits	MeasurementAccuracyStruct		F		R V	M
0x0001	SoilMoistureMeasuredValue	percent	SoilMoistureMeasurementLimits.MinMeasuredValue to SoilMoistureMeasurementLimits.MaxMeasuredValue	X		R V	M

2.15.4.1. SoilMoistureMeasurementLimits Attribute

This attribute SHALL indicate the limits for the SoilMoistureMeasuredValue attribute.

Given the measurements are in percentage, the MinMeasuredValue field in the SoilMoistureMeasurementLimits attribute SHALL NOT be less than 0 and SHALL NOT be greater than 99. The MaxMeasuredValue field in the SoilMoistureMeasurementLimits attribute SHALL NOT be less than (SoilMoistureMinMeasurableValue + 1) and SHALL NOT be greater than 100. The MeasurementType field value SHALL be set to SoilMoisture.

There SHALL only be a single entry in the AccuracyRanges list of the SoilMoistureMeasurementLimits attribute. The entry SHALL cover the full measurement range, meaning that the value of the RangeMin field SHALL be equal to the value of the MinMeasuredValue field and the value of the RangeMax field SHALL be equal to the value of the MaxMeasuredValue field. The entry SHALL only indicate a PercentMax value and the value SHALL NOT be greater than 10.00 percent.