

3.2.7.4. RemainingTime Attribute

This attribute SHALL indicate the time remaining, in 1/10ths of a second, until transitions due to the currently active command will be complete.

Changes to this attribute SHALL only be marked as reportable in the following cases:

- When it changes from 0 to any value higher than 10, or
- When it changes, with a delta larger than 10, caused by the invoke of a command, or
- When it changes to 0.

For commands with a transition time or changes to the transition time less than 1 second, changes to this attribute SHALL NOT be reported.

As this attribute is not being reported during a regular countdown, clients SHOULD NOT rely on the reporting of this attribute in order to keep track of the remaining duration.

3.2.7.5. CurrentX Attribute

This attribute SHALL indicate the current value of the normalized chromaticity value x, as defined in the CIE xyY Color Space. It is updated as fast as practical during commands that change the color.

The value of x SHALL be related to the CurrentX attribute by the relationship

$$x = \text{"CurrentX"} / 65536$$

where CurrentX is in the range from 0 to 65279 inclusive.

Changes to this attribute SHALL only be marked as reportable in the following cases:

- At most once per second or
- At the end of the movement/transition.

3.2.7.6. CurrentY Attribute

This attribute SHALL indicate the current value of the normalized chromaticity value y, as defined in the CIE xyY Color Space. It is updated as fast as practical during commands that change the color.

The value of y SHALL be related to the CurrentY attribute by the relationship

$$y = \text{"CurrentY"} / 65536$$

where CurrentY is in the range from 0 to 65279 inclusive.

Changes to this attribute SHALL only be marked as reportable in the following cases:

- At most once per second or
- At the end of the movement/transition.