

ID	Name	Type	Constraint	Quality	Fallback	Conformance
3	Transitions	list[WeeklyScheduleTransitionStruct]	max 10			M

4.3.10.5. ClearWeeklySchedule Command

This command is used to clear the weekly schedule. The Clear weekly schedule has no payload.

Upon receipt, all transitions currently stored SHALL be cleared and a default response of SUCCESS SHALL be sent in response. There are no error responses to this command.

4.3.10.6. SetActiveScheduleRequest Command

This command will set the active schedule to the provided schedule handle.

ID	Name	Type	Constraint	Quality	Fallback	Conformance
0	Schedule-Handle	octstr	max 16			M

4.3.10.6.1. ScheduleHandle Field

This field SHALL specify the value of the [ScheduleHandle](#) field on the [ScheduleStruct](#) to be made active.

4.3.10.6.2. Effect on Receipt

Upon receipt, if the [Schedules](#) attribute contains a [ScheduleStruct](#) whose [ScheduleHandle](#) field matches the value of the [ScheduleHandle](#) field, the server SHALL set the thermostat's [ActiveScheduleHandle](#) attribute to the value of the [ScheduleHandle](#) field.

Otherwise, the server SHALL return a status code of INVALID_COMMAND.

4.3.10.7. SetActivePresetRequest Command

This command will set the active preset to the provided preset handle.

ID	Name	Type	Constraint	Quality	Fallback	Conformance
0	PresetHandle	octstr	max 16	X		M

4.3.10.7.1. PresetHandle Field

This field SHALL specify the value of the [PresetHandle](#) field on the [PresetStruct](#) to be made active. If the field is set to null, that indicates there should be no active preset.