

7.6.3. Conditions

See the Base Device Type definition for conformance tags.

7.6.4. Cluster Requirements

Each endpoint supporting this device type SHALL include these clusters based on the conformance defined below.

Cluster ID	Cluster Name	Client/Server	Quality	Conformance
0x0003	Identify	Server		M
0x0404	Flow Measurement	Server		M

7.7. Humidity Sensor Device Type

A humidity sensor (in most cases a Relative humidity sensor) reports humidity measurements.

7.7.1. Revision History

Revision	Description
1	Initial Zigbee 3.0 revision
2	New data model format and notation

7.7.2. Classification

Device Type ID	Device Type Name	Superset Of	Class	Scope
0x0307	Humidity Sensor		Simple	Endpoint

7.7.3. Conditions

See the Base Device Type definition for conformance tags.

7.7.4. Cluster Requirements

Each endpoint supporting this device type SHALL include these clusters based on the conformance defined below.

Cluster ID	Cluster Name	Client/Server	Quality	Conformance
0x0003	Identify	Server		M
0x0405	Relative Humidity Measurement	Server		M