

8.17.14.9 TASKS EDSTART

Address offset: 0x020

Start the energy detect measurement used in IEEE 802.15.4 mode

8.17.14.10 TASKS EDSTOP

Address offset: 0x024

Stop the energy detect measurement

8.17.14.11 TASKS CCASTART

Address offset: 0x028

Start the clear channel assessment used in IEEE 802.15.4 mode

8.17.14.12 TASKS CCASTOP

Address offset: 0x02C

Stop the clear channel assessment