

## 8.16.7.2 TASKS\_STOP

Address offset: 0x004

## Task stopping the quadrature decoder

### 8.16.7.3 TASKS READCLRACC

Address offset: 0x008

## Read and clear ACC and ACCDBL

Task transferring the content of ACC to ACCREAD and the content of ACCDBL to ACCDBLREAD, and then clearing the ACC and ACCDBL registers. These read-and-clear operations will be done atomically.

#### 8.16.7.4 TASKS RDCLRACC

Address offset: 0x00C

## Read and clear ACC

Task transferring the content of ACC to ACCREAD, and then clearing the ACC register. This read-and-clear operation will be done atomically.