

Bit number		31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 0			
ID		A			
Reset 0x00000000		0 0			
ID	R/W	Field	Value ID	Value	Description
A	W	TASKS_GOIDLE			Force state machine to IDLE state
		Trigger		1	Trigger task

8.13.14.8 TASKS_GOSLEEP

Address offset: 0x028

Force state machine to SLEEP_A state

Bit number		31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 0			
ID		A			
Reset 0x00000000		0 0			
ID	R/W	Field	Value ID	Value	Description
A	W	TASKS_GOSLEEP			Force state machine to SLEEP_A state
		Trigger		1	Trigger task

8.13.14.9 SUBSCRIBE_ACTIVATE

Address offset: 0x080

Subscribe configuration for task ACTIVATE

Bit number		31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 0			
ID		B A A A A A A A			
Reset 0x00000000		0 0			
ID	R/W	Field	Value ID	Value	Description
A	RW	CHIDX	[0..255]		DPPI channel that task ACTIVATE will subscribe to
B	RW	EN			
		Disabled	0		Disable subscription
		Enabled	1		Enable subscription

8.13.14.10 SUBSCRIBE_DISABLE

Address offset: 0x084

Subscribe configuration for task DISABLE

Bit number		31 30 29 28 27 26 25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1 0			
ID		B A A A A A A A			
Reset 0x00000000		0 0			
ID	R/W	Field	Value ID	Value	Description
A	RW	CHIDX	[0..255]		DPPI channel that task DISABLE will subscribe to
B	RW	EN			
		Disabled	0		Disable subscription
		Enabled	1		Enable subscription

8.13.14.11 SUBSCRIBE_SENSE

Address offset: 0x088

Subscribe configuration for task SENSE