Skip to navigation

CabinetSense Wiki

- Home
- 32mm System
- Build History
- Closet Systems
- CNC
- Common Attributes
- Component Library
- Components
- Construction Templates
- Cutlist Plus Integration
- Dynamic User Components
- Elevation and Plan Dimensions
- Frequently Asked Questions
- Known Issues

Menus

- CabinetSense Menu
 - · Clear Machining
 - CNC Preferences
 - Machining Application
 - Preview Machining
- Component Menu
- Document Menu
- Help Menu
- Profiles Menu
- Scene Menu
- · Toolbars
- Plugins, Programs, and Links
- Scene and Laver Management
- Shop and Submittal Drawings
- Sketchup Tutorials
- Tips and Tricks
- Troubleshooting
- Tutorials
- Videos

CabinetSense Wiki

Preview Machining

Preview Machining overlays the cnc drillpoints on your component. This allows you to verify that the cabinet will be produced as expected.

NOTE:


- By Default, preview does not provide 3D rendering for the holes. You can control this option in the <u>preferences</u>.
- Preview does not provide any information for dadoes, blind dadoes or lock rabbets.

• CNC options are only available if you have the CNC version of CabinetSense

Usage:

• Single Component


... Request a Preview ...



... After Preview ...



 \dots Turning on Wireframe allows you to see the hidden CNC Drillpoints \dots



Page updated Report abuse