

Photo:2	Date:06/16/2022	Location:WL: 2, FL: 1
Condition Description: DETERIORATED BRICK MASONRY		Recommendation: REPLACE DETERIORATED BRICKS
Causes: AGE & WEATHERING OR MOISTURE INFILTRATION		Quantity: 90