

Overview

Overview

- The column “ALSO ON HAND (SAME MPN)” is all zero. This may be creating the quantity issues.
- When I describe a value as “in kosh” I am referring to the “Job line items” view
- General break down below in table and details and screenshots for each row are in document tabs
- Whole shortage report screenshot below this table

Kosh shortage report:
Job 8566ML

Line/Item from Kosh Job line items	Actual Shortage from Job Line Items in Kosh	Notes
8566ML-50 IC CONTROLLER TEC HI EFF 28SSOP Analog Devices LTC1923EGN#PBF	-2	Not on Shortage report, but should be. on hand qty is 0
8566ML-180 IC VREF SERIES 2.5V TSOT23-5 Analog Devices ADR03BUJZ-REEL7	-1	Not on Shortage report, but should be. on hand = 3, need 4 total
8566ML-90	+49, none	On shortage report even though Kosh says we have an overage. Shortage report says there are only 15 on hand, Kosh says 65 on hand. This item is listed 3 times on shortage report with different PCN's, it is listed once on "Job Line Items" in Kosh.
8566ML-210 IC TXRX RS-232 LP 20-TSSOP Maxim Integrated MAX3222EEUP+	0	On shortage report but we have 2 and need 2. No shortage. Listed twice on shortage report.
8566ML-310 IC DAC 12BIT 1.25V REF 10-MSOP Analog Devices AD5624RBRMZ-3	+14,none	On hand in kosh = 16, in shortage report on hand = 1
8566ML-330 ZSUB FOR ABOVE Microchip ATXMEGA128A1-AU	+8, none	On shortage report and shouldn't be. On hand qty in kosh = 10, in shortage report on hand = 1. Line 330 has a zsub line on BOM
8566ML-360 IC TXRX NON-INVERT 3.6V 20TSSOP TI SN74LVC245APWR	+47, none	Kosh on hand = 53, on shortage report there are two lines, the only differences are PCN and the on hand qty: 5 and 3.
8566ML-790 RES SMD 10K OHM 1% 1/10W 0603 Panasonic ERJ-3EKF1002V	+2222, None	On shortage report with 3 different on hand quantities and PCN's. BOM only has one component for 790

Accurate Shortages:

8566ML-170

8566ML-190

8566ML-240

What if there are no items in shortage report (Job 8566ML) that show the calculated shortages? Do we need "overage" column?

Overview

E5	ORDER QTY											8566ml-50 0 of 0	
	A	B	C	D	E	F	G	H	I	J	K		
1	Shortage Report - Job: 8566ML												
2	Generated: 2026-06-03 12:16 by parts@americancircuits.com Rev: N Order Qty: 2												
3	Shortage Items: 34 of 155 BOM lines												
4													
5	ACI PN	PCN	MPN	QTY	ORDER QTY	REQ	ITEM	ON HAND QTY	LOCATION	ON HAND (SAME M	SAME-MPN LOCATIONS		
6	8566ML-90	43024	TPS2421-2DDAR	8	2	16	8566ML-90	15	2203501	0			
7	8566ML-90	37306	TPS2421-2DDAR	8	2	16	8565ML-565	14	2204401	0			
8	8566ML-90	40550	TPS2421-2DDAR	8	2	16	8657ML-945	15	2203403	0			
9	8566ML-170	39533	AD7490BRUZ	2	2	4	8566ML-170	2	2203501	0			
10	8566ML-190	39503	TEN 30-2412WIN	1	2	2	8566ML-190	1	2203501	0			
11	8566ML-210	39532	MAX3222EEUP+	1	2	2	8566ML-210	1	2203501	0			
12	8566ML-210	33271	MAX3222EEUP+	1	2	2	8566ML-210	1	2203501	0			
13	8566ML-240	39535	LT3845AEFE#PBF	2	2	4	8566ML-240	1	2203501	0			
14	8566ML-310	33274	AD5624RBRMZ-3	1	2	2	8566ML-310	1	1602301	0			
15	8566ML-330	42636	ATXMEGA128A1-AU	1	2	2	8566ML-330	1	2203501	0			
16	8566ML-360	43563	SN74LVC245APWR	3	2	6	8565ML-595	5	2204401	0			
17	8566ML-360	42510	SN74LVC245APWR	3	2	6	8566ML-360	3	2203501	0			
18	8566ML-370	42616	CRA2512-FZ-R100ELF	2	2	4	8566ML-370	2	2203501	0			
19	8566ML-690	37227	CRCW0603000020EA	37	2	74	8608ML-10	30	2201402	0			
20	8566ML-790	21257	ERJ-3KF1002V	74	2	148	7143L-36	75	1604006	0			
21	8566ML-790	22484	ERJ-3KF1002V	74	2	148	8342ML-525	7	1601004	0			
22	8566ML-790	5842	ERJ-3KF1002V	74	2	148	7944L-36	100	1503009	0			
23	8566ML-830	22528	ERJ-3KF10R0V	6	2	12	8342ML-285	8	1601004	0			
24	8566ML-870	39489	BSC084P03N53GATMA1	2	2	4	8566ML-870	3	2203501	0			
25													
26													
27													

Convert to table X

- Questions:
- Why is there no formal shortage column? Let's add that in so they dont have to do the math.
 - Is Order quantity column necessary since the order qty is at the top?

8566ml-90

Line 90

On shortage report even though Kosh says we have an overage of +49. Shortage report says there are only 15 on hand, Kosh says 65 on hand. This item is listed 3 times on shortage report with different PCN's, it is listed once on "Job Line Items" in Kosh.

Job Line Items (122 rows)

Red = Shortage

Search parts...

Line	PCN	ACI PN	Description	MPN	QTY	REQ	On Hand	Location	Cost	Shortage
10	36267	8566ML-10	CAP CER 1UF 25V X7R 0603 Murata	GCJ188R71E105KA01D	1	2	70	1603007	\$0.00	+68
20	36227	8566ML-20	CAP CER 2.2UF 25V X6S 0603 Murata	GRT188C81E225KE13D	1	2	50	1603007	\$0.00	+48
30	36253	8566ML-30	ZSUB FOR ABOVE ECS	ECS-160-18-23A-EN-TR	1	2	33	2203501	\$0.00	+31
50	-	8566ML-50	IC CONTROLLER TEC HI EFF 28SSOP Analog Devices	LTC1923EGN#PBF	1	2	0	-	\$0.00	-2
60	42613	8566ML-60	IC QUAD 2-1 DATA SEL/MUX 16TSSOP TI	SN74LVC157APWR	1	2	95	2203501	\$0.00	+93
70	42500	8566ML-70	IC OPAMP DIFF 3.2MHZ RRO 8MSOP Analog Devices	LTC1992HMS8#PBF	1	2	7	2203501	\$0.00	+5
80	42637	8566ML-80	IC MOSFET DVR 9A NON-INV 8DFN Microchip	TC4422AVMF	4	8	17	2203501	\$2.13	+9
90	36255	8566ML-90	IC CTRLR HOT SWAP 3-20V 8SOPWR Texas Instruments	TPS2421-2DDAR	8	16	65	1604006	\$0.00	+49

Line	DESC	MAN	MPN	ACI PN	QTY	POU	LOC	35	STK	ORD (ATTR)	ORD (FLR)	ORDER(ACTUAL)	PAID	DIST
10	CAP CER 1UF 25V X7R 0603	Murata	GCJ188R71E105KA01D	8566ML-10	1	SMT	C275	\$0.085	110	35	0			
20	CAP CER 2.2UF 25V X6S 0603	Murata	GRT188C81E225KE13D	8566ML-20	1	SMT	C23	\$0.084	110	35	0			
30	CRYSTAL 16.000MHZ 18PF SMD	ECS	ECS-160-18-23A-EN-TR	8566ML-30	1	SMT	Y2	\$0.707	98	35	0			
30	ZSUB FOR ABOVE	ECS	ECS-160-18-23A-EN-TR	8566ML-30	1	SMT	Y2	\$0.782	0	35	0			
50	IC CONTROLLER TEC HI EFF 28SSOP	Analog Devices	LTC1923EGN#PBF	8566ML-50	1	SMT	U69	\$26.89	0	35	35	35	26.890	Mouser
60	IC QUAD 2-1 DATA SEL/MUX 16TSSOP	TI	SN74LVC157APWR	8566ML-60	1	SMT	U68	\$0.269	80	35	80	80	0.239	Mouser
70	IC OPAMP DIFF 3.2MHZ RRO 8MSOP	Analog Devices	LTC1992HMS8#PBF	8566ML-70	1	SMT	U47	\$5.30	6	35	35	35	4.232	Digi-Key
80	IC MOSFET DVR 9A NON-INV 8DFN	Microchip	TC4422AVMF	8566ML-80	4	SMT	U44, U61, U63, U63	2.130	17	143	150	150	2.010	Mouser
90	IC CTRLR HOT SWAP 3-20V 8SOPWR	Texas Instruments	TPS2421-2DDAR	8566ML-90	8	SMT	U38, U37, U38, U41, U45, U49, U52, U55	\$1.41	50	280	300	300	1.42368	Digi-Key
90	ZSUB FOR ABOVE	Texas Instruments	TPS2421-2DDA	8566ML-90	8	SMT	U38, U37, U38, U41, U45, U49, U52, U55	\$2.04	0	0	0		0.007	Mouser

E5

ORDER QTY

A	B	C	D	E	F	G	H	I	J	K
Shortage Report - Job: 8566ML										
Generated: 2026-06-03 12:16 by parts@americancircuits.com Rev: N Order Qty: 2										
Shortage Items: 34 of 155 BOM Lines										
ACI PN	PCN	MPN	QTY	ORDER QTY	REQ	ITEM	ON HAND QTY	LOCATION	ON HAND (SAME V	SAME-MPN LOCATIONS
8566ML-90	43024	TPS2421-2DDAR	8	2	16	8566ML-90	15	2203501	0	
8566ML-90	37306	TPS2421-2DDAR	8	2	16	8565ML-565	14	2204401	0	
8566ML-90	40550	TPS2421-2DDAR	8	2	16	8657ML-945	15	2203403	0	
8566ML-170	39533	A07490BRUZ	2	2	4	8566ML-170	2	2203501	0	
8566ML-190	39503	TEN 30-2412WIN	1	2	2	8566ML-190	1	2203501	0	
8566ML-210	39532	MAX3222EUP+	1	2	2	8566ML-210	1	2203501	0	
8566ML-210	33271	MAX3222EUP+	1	2	2	8566ML-210	1	2203501	0	
8566ML-240	39535	LT3845AEF#PBF	2	2	4	8566ML-240	1	2203501	0	
8566ML-310	33274	AD5624BRMZ-3	1	2	2	8566ML-310	1	1602301	0	
8566ML-330	42636	ATXMEGA128A1-AU	1	2	2	8566ML-330	1	2203501	0	
8566ML-360	43563	SN74LVC245APWR	3	2	6	8565ML-595	5	2204401	0	
8566ML-360	42510	SN74LVC245APWR	3	2	6	8566ML-360	3	2203501	0	
8566ML-370	42616	CRA2512-FZ-R100ELF	2	2	4	8566ML-370	2	2203501	0	
8566ML-690	37227	CRCW0603000020EA	37	2	74	8608ML-10	30	2201402	0	
8566ML-790	21257	ERJ-3KF1002V	74	2	148	7143L-36	75	1604006	0	
8566ML-790	22484	ERJ-3KF1002V	74	2	148	8342ML-525	7	1601004	0	
8566ML-790	5842	ERJ-3KF1002V	74	2	148	7944L-36	100	1503009	0	
8566ML-830	22528	ERJ-3KF10R0V	6	2	12	8342ML-285	8	1601004	0	
8566ML-870	39489	BSC0840P3N53GATMA1	2	2	4	8566ML-870	3	2203501	0	

Convert to table

8566ML-310

8566ML-310

Shortage report and Kosh job line items state two different quantities

On hand in kosh = 16, in shortage report on hand = 1

Inventory table:

Inventory Table													
Click "Refresh" button to see latest updates Page 1 of 1													
PCN	ITEM NUMBER	MPN	DESCRIPTION	DC	ON HAND QTY	LOC FROM	LOC TO	MFG QTY	MSD	PO	VENDOR	COST	ACTION
42803	8657ML-780	AD5624RBRMZ-3	IC DAC 12BIT 1.25V REF 10-MSOP	2235	4	Count Area	MFG Floor	30	1	8565-022	-	0.0000	  
42501	8566ML-310	AD5624RBRMZ-3	IC DAC 12BIT 1.25V REF 10-MSOP	2235	3	-	2203501	0	0	8608-006	-	0.0000	  
40488	8657ML-780	AD5624RBRMZ-3	IC DAC 12BIT 1.25V REF 10-MSOP	1148	0	-	MFG Floor	5	0	8607-027	-	0.0000	  
39470	8566ML-310	AD5624RBRMZ-3	IC DAC 12BIT 1.25V REF 10-MSOP	2111	2	-	2203501	0	1	8566-009	-	0.0000	  
36272	8566ML-310	AD5624RBRMZ-3	IC DAC 12BIT 1.25V REF 10-MSOP	1213	10	-	1604006	0	1	-	-	-	  
33274	8566ML-310	AD5624RBRMZ-3	IC DAC 12BIT 1.25V REF 10-MSOP	8546	1	-	1602301	0	1	6707-025	-	-	  

8566ML-360

On hand quantities are different in shortage report (listed twice) and on job line items in Kosh
Kosh on hand = 53
PCN on Kosh is different from PCN on shortage report

A	B	C	D	E	F	G	H	I	J	K	8566L
Shortage Report - Job: 8566ML											
Generated: 2026-06-03 12:16 by parts@americancircuits.com Rev: N Order Qty: 2											
Shortage Items: 34 of 155 BOM lines											
ACI PN	PCN	MPN	QTY	ORDER QTY	REQ	ITEM	ON HAND QTY	LOCATION	ON HAND (SAME V	SAME-MPN LOCATIONS	
8566ML-360	43563	SN74LVC245APWR	3	2	6	8565ML-595	5	2204401	0		
8566ML-360	42510	SN74LVC245APWR	3	2	6	8566ML-360	3	2203501	0		
360	39475	8566ML-360	IC TXRX NON-INVERT 3.6V 20TSSOP				SN74LVC245APWR	3	6	53	2203501 \$0.00 +47

8566ML-790

8566ML-790

This part is on shortage report with 3 different on hand quantities and PCN's. BOM only has one component for line 790.

On Job line item's there is no shortage, there is an overage of 2222

Shortage Report - Job: 8566ML											
Generated: 2026-06-03 12:16 by parts@americancircuits.com Rev: N Order Qty: 2											
Shortage Items: 34 of 155 BOM lines											
ACI PN	PCN	MPN	QTY	ORDER QTY	REQ	ITEM	ON HAND	QTY	LOCATION	ON HAND (SAME M	
8566ML-790	21257	ERJ-3EKF1002V	74	2	148	7143L-36	75		1604006	0	
8566ML-790	22484	ERJ-3EKF1002V	74	2	148	8342ML-525	7		1601004	0	
8566ML-790	5842	ERJ-3EKF1002V	74	2	148	7944L-36	100		1503009	0	

790	36278	8566ML-790	RES SMD 10K OHM 1% 1/10W 0603	ERJ-3EKF1002V	74	148	2370	1304813	\$0.00	+2222
Panasonic										

								Build Qty					
Line	DESC	MAN	MPN	ACI PN	QTY	POU	LOC	35	STK	ORD (ATTR)	ORDD (FLR)	ORDI	
790	RES SMD 10K OHM 1% 1/10W 0603	Panasonic	ERJ-3EKF1002V	8566ML-790	74	SMT	R4, R6, R8, R9, R11, R19, R25, R26, R29, R33, R42, R48, R52, R53, R54, R55, R59, R60, R61, R66, R71, R73, R93, R98, R99, R103, R110, R112, R113, R114, R122, R134, R139, R156, R157, R163, R165, R166, R172, R173, R174, R175, R176, R189, R191, R199, R202, R208, R209, R212, R214, R220, R223, R228, R3, R12, R63, R129, R237	\$0.012	5057	2590	0		
800	RES 0.015 OHM 1% 1/2W 1206	Starknole	CSP1206FK150 0	8566ML-800	5	SMT		50107	230	175	200	200	