

CMTA + City of Austin Transit Baseline

Section 1 Presentation Packet

Section A - Amenity Conditions: What Riders Are Missing Right Now

Date: April 18, 2026

Prepared for: Agenda submission and Section 1 presentation

1) Section Scope for This Presentation

This packet is intentionally limited to the first section of the analysis:

- Section A - Amenity Conditions: What Riders Are Missing Right Now

Use this packet when you only need to present the opening evidence block and not the full multi-section analysis.

2) Agenda Submission Ready Summary

Agenda Item Title

Transit Stop Amenity Conditions at High-Priority Stops (Baseline Section 1)

Requested Discussion Focus

- Baseline evidence on shelter and bench gaps at high-priority stops.
- Immediate implications for rider safety, accessibility, and service quality.
- Initial corrective-action framing for next meeting cycle.

Time Allocation (Suggested)

- 1 minute: Why this section matters.
 - 2 minutes: Core metrics and evidence.
 - 2 minutes: Top stop examples and risk concentration.
 - 1 minute: Immediate ask.
-

3) Core Numbers to Repeat Verbatim

- 80% of high-priority stops are missing shelter.
- 64% of high-priority stops are missing benches.
- All analyzed high-priority stops in this section show significant amenity deficits.

Primary source: output/tables/evidence_matrix.csv

4) First-Section Narrative (Presentation Copy)

Finding

The stops serving the most riders are among the worst-equipped in the system.

The high-priority stops were assessed against two baseline amenities: shelter and benches. For transit-dependent riders, these are functional necessities.

- 80% of high-priority stops are missing shelter entirely.
- 64% are missing benches entirely.

Why This Matters

At locations with high service activity, missing shelter and seating increase weather exposure, standing burden, and accessibility risk.

Priority Stop Examples to Name

1. 1609 Lavaca/17th (Midblock)
 2. Guadalupe/16th Street
 3. Lavaca/4th
 4. Guadalupe/W. 21st Street
 5. UT Dean Keeton Station (NB)
-

5) Section 1 Slide Content (Ready to Present)

Slide Title

High-Demand Stops Have Large Amenity Gaps

On-slide bullets

- 80% of high-priority stops are missing shelter.
- 64% of high-priority stops are missing benches.
- Basic rider protections are missing where service is concentrated.

Speaker Notes

- This is a baseline built from reproducible public data.
 - These are not fringe stops; these are high-service locations.
 - The first action threshold is straightforward: close shelter and bench gaps at top-risk stops.
-

6) Visual for Section 1

Recommended chart:




Figure 1: Top 10 risk stops chart

Figure source: output/figures/top10_risk_stops_bar.png

7) Immediate Ask (Section 1 Only)

1. Approve targeted shelter and bench corrective action at top-risk stops.
2. Require monthly progress reporting on shelter and bench installation status.
3. Carry unresolved amenity gaps forward as standing agenda items until corrected.

8) Source Materials Included in This Packet

- reports/Qualitative_Summary.md (Section A)
- PRESENTATION_PACK.md (Slides 1-4 content alignment)
- reports/CMTA_20_Minute_Presenter_Cheat_Sheet.md (opening and concern framing)
- output/tables/evidence_matrix.csv
- output/tables/top10_high_risk_stops_table.csv

- `output/figures/top10_risk_stops_bar.png`