

HEWLETT-WOODMERE PUBLIC SCHOOLS

Board of Education Annual Facilities Tour - Wednesday, December 20, 2023

** The site visit will start at the RECREATION BUILDING at 7:00 pm			
			Priority
Hewlett High School 7:00 pm - 7:30 pm			Rank 1 (High) - 5 (Low)
a.	Future Consideration	Backup Systems Generator - \$ TBD	
b.	Future Consideration	Door & Door Hardware Replacement - \$ TBD	
c.	Future Consideration	Football Locker Room Refurishment - \$ 455,000	
d.	Future Consideration	Tennis Court Addition & Replacement - \$ TBD	
e.	Future Consideration	Fitness Center Addition (JAG Arch) - \$ 19.1 mil (original estimate)	
f.	Future Consideration	New Concession/Field House/ 2-Story Team Room Addition - \$ TBD	
g.	Future Consideration	Additional Exterior CCTV Cameras & DVR for Field - \$ TBD	
h.	Future Consideration	Additional Bleacher System for Football Field - \$ 300,000	
i.	Future Consideration	Exterior LED Lighting Replacement Project - Incentives	
j.	Future Consideration	Paving Project - Various Areas - \$ 550,000	
k.	Future Consideration	Oil Tank Removal - \$ TBD	
l.	Future Consideration	Creation of "Right Turn Only" Lane onto East Rockaway Road - \$ TBD	
m.	Future Consideration	Natatorium Restoration - \$ TBD	
n.	Future Consideration	Electrical Panel Upgrades - \$ 400,000	
o.	Future Consideration	VAT Abatement & Floor Tile Replacement - \$ 400,000	
p.	Future Consideration	Full Kitchen Renovation - \$ TBD	
q.	Future Consideration	Kitchen Serving Line Renovation - \$ 280,000 (original estimate)	
r.	Future Consideration	Robotics Room Creation (Room LC 11) - \$ TBD	
s.	Future Consideration	Little Theatre Upgrades - \$ TBD	
t.	Future Consideration	PACE Lab Upgrades - \$ TBD	
u.	Future Consideration	Senior Center Renovation - \$ TBD	
a.	In Progress	HVAC System - Building Wide Upgrade	
b.	In Progress	Original Boiler Room Abatement & Conversion of Space	
c.	In Progress	Auditorium & Stage Renovation	
c.	In Progress	Science Lab Renovations	
d.	In Progress	New Synthetic Turf - Softball Field	
e.	In Progress	Replacement of Existing Synthetic Turf & Track Surface	
f.	In Progress	Pedestrian Path to Football Field	
g.	In Progress	Pool Piping Repairs	
a.	Completed	PPS Office - Carpet Removal & New EVT Floor Installation	
b.	Completed	Main Office - Carpet Removal & New EVT Floor Installation	
c.	Completed	Main Entrance Portico & Athletic Field Illuminated Signage	
d.	Completed	Girls Team Locker Room Renovation	

Facilities Planning

Project Review Status

- **SED PROJECT STATUS:**

- If you have a question about the status of your project awaiting review, please consult our [status reports page](#) first. Upon receipt of your project, your project manager will call you to identify missing items, if necessary. Upon architectural/mechanical review, our A/Es will do likewise.

- **SED PROJECT REVIEW STATUS AS OF 12/06/2023:**

- **Architectural Review:**

- Average time for final architectural review will be about 18-20 weeks.
- The next architectural review will be 23-0169. It was logged into the review system on 07/28/23.

- **Engineering Review:**

- Average time for final engineering review will be about 18-20 weeks.
- The next engineering review will be 23-0164. It was logged into the review system on 07/28/23.
- The most recent submission has review number 23-1137. It was logged into the review system on 12/06/2023.
- The last review number assigned for 2022 was 22-2492. It was logged into the review system on 06/30/2023.

[Return to Facilities Planning Home Page](#)

Building Condition Survey and Visual Inspection

The 2019 Enacted Budget included changes to Education Laws §409-d (Comprehensive public school building safety program) and §3641 (Special apportionments and grants-in-aid to school districts). These are the sections of state law that relate to the five year cycle for building condition surveys (BCS) and the requirement for annual visual inspections (AVI).

Under the new statute, districts must conduct Building Condition Surveys (BCS) on a staggered schedule as assigned by the Commissioner in calendar years 2020 through 2024, and every five years on that same five year cycle thereafter. To develop the schedule, NYSED created five groupings within each of the State's Labor Market Regions (LMR). One for each year. Data regarding the number of instructional buildings per district was used to equally distribute the number of buildings to be surveyed in each BCS cohort year. Next, data from the 2015 Building Condition Survey was used to assign groups with the highest number of buildings identified as 'poor' or 'unsatisfactory' to BCS cohort years 2020 and 2021.

For some districts, the new schedule will stretch out the period between the intensive building condition surveys for several years. To address this, the legislature chose to partially reinstate the visual inspection requirement, although it is no longer annual. Under the new statute, districts whose place in the new Building Condition Survey cycle means that they have not yet conducted a building condition survey by the end of calendar year 2020, and then by the end of calendar year 2022, must conduct a visual inspection in those years. Otherwise and thereafter, visual inspections need only be conducted as deemed necessary by the Commissioner.

2020 BUILDING CONDITION SURVEY AND VISUAL INSPECTION (copied from Welcome webpage 11-16-2020)

ACTION REQUIRED: Must be completed by December 31, 2020 and submitted by March 1, 2021

2020 Building Condition Survey and 2020 Visual Inspections

The 2020 Building Condition Survey (BCS) and 2020 Visual Inspection (VI) districts deadlines are looming. These surveys and inspections must be completed by 12/31/20 and submitted by 03/01/21.

Although NYSED has requested that the deadline (which is in law) be extended, an extension has not yet been provided. In the absence of such response, we encourage all districts to prepare to complete their assigned BCSs and VIs timely. Districts assigned to the 2020 BCS grouping may lose the BCS reimbursement if there is no extension and the surveys are not completed according to the statutory timelines.

Please reference the website, **Building Condition Survey and Visual Inspection:**

<https://www.p12.nysed.gov/facplan/BldgCondSurv.htm>

- 2020-2024 Building Condition Survey - [Assignment List](#)  (115KB) (07/28/20)
- 2020 and 2022 Visual Inspection - [Assignment Lists](#)  (181 KB) (11/22/19)

ACTION REQUIRED: Due March 1, 2021

Submittal of 2020 Building Condition Survey

- Each BOCES and public school district that has been assigned to complete a Building Condition Survey for all normally occupied buildings in calendar year 2020, must submit the survey data electronically in the SED Monitoring and Vendor Performance System (SED Monitoring), which may be accessed at: <http://portal.nysed.gov>.
- Designated personnel should log on to the NYSED Business Portal using their existing State Education Department Delegated Administrator Account System (SEDDAS) account and password. Once logged in, click on the link to the "SED Monitoring and Vendor Performance System," then click on "Facilities," then click "2020 Building Condition Survey."
- If you have questions or problems accessing the business portal or the SED Monitoring and Vendor Performance System, contact the SEDDAS helpdesk at SEDDAS@nysed.gov
- Additional information regarding the 2020 Building Condition Survey including BOCES/public school district assignments, instructions and answers to frequently asked questions can be found on the Office of Facilities Planning [website](#).
- Questions regarding the submission of the 2020 Building Condition Survey can be directed to the NYSED Office of Facilities Planning at (518) 474-3906 or emscfp@nysed.gov.

2020-2024 Building Condition Survey

- 2020-2024 Building Condition Survey - [Assignment List](#)  (115KB) (07/28/20)
- 2020 Building Condition Survey - [Instructions](#)  (181KB) (10/16/20)
- 2020 Building Condition Survey - [Sample Document](#)  (3,165KB) (02/12/20)
- 2020 Building Condition Survey - [Sample Building & System Rating Information](#)  (53KB) 01/06/20
- Building Condition Survey - [Frequently Asked Questions](#)  (1,042KB) (01/06/20)

2020 and 2022 Visual Inspection

- 2020 and 2022 Visual Inspection - [Assignment List](#)  (181 KB) (11/22/19)
- 2020 Visual Inspection - [Instructions](#)  (167KB) (03/05/20)
- 2020 Visual Inspection - [Sample Document](#)  (1,952KB) (02/12/20)
- 2020 Visual Inspection - [Sample Building & System Rating Information](#)  (53KB) 01/29/20
- Visual Inspection - [Frequently Asked Questions](#)  (928KB) (01/29/20)

2022 Building Condition Survey

- [2022 Building Condition Survey](#) . The surveys are in a zip file and are district-by-district in pdf format.

2021 Building Condition Survey

- [2021 Building Condition Survey](#) . The surveys are in a zip file and are district-by-district in pdf format.

2020 Building Condition Survey

- [2020 Building Condition Survey](#) . The surveys are in a zip file and are district-by-district in pdf format.

2015 Building Condition Survey

- [2015 Building Condition Survey](#) . The surveys are in a zip file and are district-by-district in pdf format.

2013 Annual Visual Inspection

2013 BCS/AVI Report data is not available. (12/30/16)

Hewlett Woodmere Union Free School District

	Prefunded Projects
	Capital Fund Projects 2015-2016
	"TBD" Projects (additional scope/information required)

G.W. Hewlett High School - 006

Description of Work	FY 16/17	FY 17/18	FY 18/19	FY 19/20	FY 20/21	Inspection Comments
1.0 Site Utilities						
1.1 Water					\$20,000	Install well for lawn irrigation
1.2 Site Sanitary						
1.3 Site Gas	\$125,000					Upgrade gas shut-off valves, controls at Kitchen & Sci Rms
1.4 Site Fuel Oil		\$30,000				Properly decommission abandoned tank
1.5 Site Electrical	\$60,000			TBD		New lighting outside Library (\$60,000); new display sign (TBD)
1.6 Drainage Systems						
1.7 Water Collection, Retainage						
2.0 Site Features						
2.1 Pavement	\$100,000				\$550,000	Pave new path to field (\$100,000), select areas (\$550,000)
2.2 Sidewalks						
2.3 Playgrounds, Play Equipment						
2.4 Athletic Fields, Structures	\$175,000				\$200,000	Replace perim. fencing, gates; add'l bleachers (\$175,000)
3.0 Substructure						
3.1 Foundations		\$100,000				Excavate/backfill foundation repairs at pool bldg.
4.0 Building Envelope						
4.1 Structural Floors			\$6,225,000			New concessions/toilet bldg., new 2-story team rm add'n
4.2 Exterior Walls, Columns		\$300,000			\$75,000	Repointing, masonry work; Infill unit vent op'gs with FRP panels
4.3 Chimneys						
4.4 Parapets						
4.5 Exterior Doors						
4.6 Exterior Steps, Stairs, Ramps						
4.7 Fire Escapes						
4.8 Windows	\$400,000	\$400,000	\$400,000			Replace exist'g windows (phased, select areas throughout)
4.9 Roof and Skylights	\$550,000					Select roofing repairs, incl. gymnasium, science rms
5.0 Interior Spaces					TBD	Library renovations (scope TBD)
5.1 Interior Bearing Walls			\$6,562,500			Conversion of boiler room into expanded Cafeteria, Student Ctr.
5.2 Interior Walls				\$1,137,500		Alterations at Weight Room (\$682,500) & Locker Rm (\$455,000)
5.3 Carpet						
5.4 Resilient Tiles, Sheet Flrg.					\$450,000	VAT abatement, VCT replacement (select rms throughout)
5.5 Hard Flooring	\$100,000					Replacement of pool lobby flooring - scope TBD
5.6 Wood						
5.7 Ceilings			TBD			Music Lab renovations (scope TBD); Gym equipment
5.8 Lockers						
5.9 Interior Doors	\$100,000			\$600,000		Replace select doors/h/ware, incl. auditorium doors (\$100,000)
5.10 Interior Stairs			TBD			Floor repairs near Room 148, corridor and stairs
5.11 Elevators & Lifts						
5.12 Interior Electrical		\$225,000				Upgrade approx. 20 panel boards and feeders
5.13 Lighting Fixtures					\$30,000	Replace select basement and exit lighting
5.14 Communications Systems				\$180,000	TBD	Provide wireless clock system; new Broadcast Studio (TBD)
5.15 Swimming Pool Systems	\$450,000					Pool Upgrades - finishes, equipment & controls
6.0 Plumbing						
6.1 Water Distribution System				\$5,000		Add kitchen pot sink
6.2 Plumbing Drainage System				\$40,000		Provide 140 degree water to the Kitchen
6.3 Hot Water Heaters				\$115,000		Replace select plumbing fixtures for ADA compliance
6.4 Plumbing Fixtures						
7.0 HVAC Systems						
7.1 HVAC Systems	\$10,500		TBD			Assess ex'g HVAC system (\$10,500); solar system for Pool (TBD)
7.2 Heat Generating Systems		\$885,000	TBD			Remove ex'g boiler, piping (\$885,000); pool boiler work (TBD)
7.3 Heating Fuel/Energy Systems				\$425,000		Allowance to replace existing kitchen/servery equipment
7.4 Cooling Generating Sys.		TBD				Repairs/Upgrades to Geothermal system
7.5 Air Handling Equipment					\$232,500	Provide new HVAC units for team locker rm., select areas
7.6 Piped Heating & Cooling Sys.	\$20,000					New "Basement" Project (scope TBD)
7.7 Ducted Heating & Cooling Sys.					\$75,000	Upgrade exhaust systems in bathrms., team/locker rms.
7.8 HVAC Control Systems					\$150,000	Replace remaining pneumatic controls, upgrade DDC
8.0 Fire Safety Systems						
8.1 Fire Alarm Systems						
8.2 Smoke Detection Systems						
8.3 Fire Suppression Systems						
8.4 Emergency/Exit Ltg. Systems						
8.5 Emerg./Standby Power Sys.	\$30,000					New backup systems generator for select items
Work Subtotal	\$2,120,500	\$1,940,000	\$13,187,500	\$2,502,500	\$1,782,500	\$21,533,000
22% Professional Fees/ Contingency:	\$466,510	\$426,800	\$2,901,250	\$550,550	\$392,150	
4% Inflation/yr:		\$94,672	\$1,287,100	\$366,366	\$347,944	
Construction Total	\$2,587,010	\$2,461,472	\$17,375,850	\$3,419,416	\$2,522,594	\$28,366,342

Hewlett Woodmere Union Free School District

	Prefunded Projects
	Capital Fund Projects 2015-2016
	"TBD" Projects (additional scope/information required)

Alternative Learning Program/ Rec. Building - 007

Description of Work	FY 16/17	FY 17/18	FY 18/19	FY 19/20	FY 20/21	Inspection Comments
1.0 Site Utilities						
1.1 Water						
1.2 Site Sanitary						
1.3 Site Gas						
1.4 Site Fuel Oil				\$125,000		Replace fuel oil tank and monitoring system
1.5 Site Electrical				\$50,000		Provide new 400 amp electric service
1.6 Drainage Systems						
1.7 Water Collection, Retainage				\$75,000		Allowance to address drainage issues at E. Rockaway Rd.
2.0 Site Features						
2.1 Pavement						
2.2 Sidewalks						
2.3 Playgrounds, Play Equipment						
2.4 Athletic Fields, Structures						
3.0 Substructure						
3.1 Foundations						
4.0 Building Envelope						
4.1 Structural Floors						
4.2 Exterior Walls, Columns						
4.3 Chimneys						
4.4 Parapets						
4.5 Exterior Doors						
4.6 Exterior Steps, Stairs, Ramps				\$20,000		Repairs to exterior concrete steps
4.7 Fire Escapes						
4.8 Windows				\$195,000		Replace existing windows throughout
4.9 Roof and Skylights				\$120,000		Replace existing roof throughout
5.0 Interior Spaces						
5.1 Interior Bearing Walls						
5.2 Interior Walls						
5.3 Carpet				\$15,000		Replace existing carpet and wall base in select rooms
5.4 Resilient Tiles, Sheet Flg.				\$12,500		Replace VAT floor tile in select rooms
5.5 Hard Flooring						
5.6 Wood						
5.7 Ceilings						
5.8 Lockers						
5.9 Interior Doors				\$15,000		Replace select interior doors and hardware
5.10 Interior Stairs						
5.11 Elevators & Lifts						
5.12 Interior Electrical						
5.13 Lighting Fixtures						
5.14 Communications Systems						
5.15 Swimming Pool Systems						
6.0 Plumbing						
6.1 Water Distribution System						
6.2 Plumbing Drainage System						
6.3 Hot Water Heaters				\$7,500		Replace domestic water heater
6.4 Plumbing Fixtures				\$750		Replace 2nd Floor toilet
7.0 HVAC Systems						
7.1 HVAC Systems						
7.2 Heat Generating Systems				\$75,000		Replace existing boiler with new, including safety controls
7.3 Heating Fuel/Energy Systems						
7.4 Cooling Generating Sys.						
7.5 Air Handling Equipment				\$150,000		Provide new cooling equipment to all occupied spaces
7.6 Piped Heating & Cooling Sys.						
7.7 Ducted Heating & Cooling Sys.				\$175,000		Provide new heating system to all occupied spaces
7.8 HVAC Control Systems						
8.0 Fire Safety Systems						
8.1 Fire Alarm Systems						
8.2 Smoke Detection Systems						
8.3 Fire Suppression Systems						
8.4 Emergency/Exit Ltg. Systems						
8.5 Emerg./Standby Power Sys.						
Work Subtotal	\$0	\$0	\$0	\$1,035,750	\$0	\$1,035,750
22% Professional Fees / Contingency:	\$0	\$0	\$0	\$227,865	\$0	
4% Inflation/yr:		\$0	\$0	\$151,634	\$0	
Construction Total	\$0	\$0	\$0	\$1,415,249	\$0	\$1,415,249

Hewlett Woodmere Union Free School District	
Construction Cost Totals	

Description of Work	FY 16/17	FY 17/18	FY 18/19	FY 19/20	FY 20/21	Building Subtotals
---------------------	----------	----------	----------	----------	----------	--------------------

[illegible]