

workshop log - page 1

Maintenance Incident Report, Casablanca Fleet Depot. Reefer compressor (TRK-88, Thermo King) flagged 09:30 yesterday - severe drive-belt wear; replacement part on backorder. Vehicle cleared for short-run service with deferred maintenance notice.