Pioneer Body and Paint

Vehicle Repair Estimate

Estimate number: EST-231406
Estimate date: 2015-01-22
Customer: Samuel Hayes
Vehicle: 1997 Subaru Forrestor
Insurer: Casefile Mutual Insurance
Claim number: CLM-2015-00341
Policy number: 728600

Estimated cost of repair (USD)

Description	Type	Amount
Headlamp assembly	Parts	6,528.00
Front fender	Parts	8,231.00
Body labor	Labor	13,197.00
Paint and materials	Paint	17,404.00
Estimate total		**45,360.00**

This estimate is based on a visual inspection. Hidden damage found during repair may change the final cost.