Maple Street Collision

Vehicle Repair Estimate

Estimate number: EST-653229
Estimate date: 2015-03-04
Customer: Kevin Bennett
Vehicle: 1999 Saab 93
Insurer: Casefile Mutual Insurance
Claim number: CLM-2015-00974
Policy number: 354481

Estimated cost of repair (USD)

Description	Type	Amount
Fender repair	Parts	1,134.00
Side mirror assembly	Parts	738.00
Body labor	Labor	570.00
Paint and materials	Paint	1,158.00
Estimate total		**3,600.00**

This estimate is based on a visual inspection. Hidden damage found during repair may change the final cost.