Riverside Auto Body

Vehicle Repair Estimate

Estimate number: EST-823075
Estimate date: 2015-01-23
Customer: James Carter
Vehicle: 1998 Mercedes ML350
Insurer: Casefile Mutual Insurance
Claim number: CLM-2015-00362
Policy number: 806081

Estimated cost of repair (USD)

Description	Type	Amount
Rocker panel	Parts	14,050.00
Side curtain airbag	Parts	9,696.00
Side mirror assembly	Parts	11,865.00
Front door shell	Parts	8,439.00
Body labor	Labor	12,951.00
Paint and materials	Paint	12,929.00
Estimate total		**69,930.00**

This estimate is based on a visual inspection. Hidden damage found during repair may change the final cost.