Command Window

Radius Of The Hole (Exa: [.125, .25]) [=> in]: [0.1250, 0.2500, 0.3750, 0.5000, 0.6250, 0.7500]
Width Of The Bar [=> in]: 3.0
Thickness Of The Bar [=> in]: 1/4

\$\forall \text{ Allowable Stress (avg) [=> ksi]: 16}