به نام خدا

گزارش کار آز ریز شماره ۹

9571014 اميرمحمد پيرحسين لو

۹۴۲۲۰۲۴ محمد رهبر

شرح كلى آزمايش:

در این آزمایش قصد داریم عملکرد زمانسنج/شمارنده ۰ را در حالت CTC و حالت عملکرد عادی بررسی کنیم.

به این منظور، به صورت تناوبی یک LED را به کمک زمانسنج روشن و خاموش می کنیم.

الف)

$$\frac{4*256*1024}{1024*1024 Hz} = 1s$$

به دلیل اینکه زمانسنج ۴ بار overflow شده است و هر بار زمانسنج تا ۲۵۵ شمرده است و تقسیم کننده هم روی ۱۰۲۴ تنظیم شده است، صورت کسر به شکل بالا درآمده است.

به دلیل اینکه کلاک میکرو را روی 1MH تنظیم کرده ایم، مخرج کسر به شکل بالا درآمد.

تنظیمات زمانسنج در حالت عادی:

تنظیمات زمانسنج در حالت CTC:

```
TCNT0 = 0;

OCR0 = 0;

TCCR0 |= (1<<CS02) |(0<<CS01) |(1<<CS00);

TIMSK |= (1<<OCIE0);

TCNT0 = 0;

OCR0 = 127; //frequency = 2Hz

TCCR0 |= (1<<CS02) |(0<<CS01) |(1<<CS00) |(1<<WGM01);

TIMSK |= (1<<OCIE0);
```

```
#include <avr\io.h>
#include <avr\interrupt.h>
#include <util\delay.h>
#include <stdio.h>
#include <string.h>
#include <stdlib.h>
#include <string.h>
#define degree_sysmbol 0xdf
  LCD16x2 4 bit ATmega16 interface
  http://www.electronicwings.com
*/
#define LCD_Dir DDRA
                                   /* Define LCD data port direction */
#define LCD_Port PORTA
                                    /* Define LCD data port */
#define RS PA1
                  /* Define Register Select (data reg./command reg.)
signal pin */
#define EN PA3
                                     /* Define Enable signal pin */
volatile int currentRow = 1;
volatile char dogment[10];
volatile int column = 1;
volatile int overflowCounter = 0;
void LCD_Command( unsigned char cmnd )
{
       LCD_Port = (LCD_Port & 0x0F) | (cmnd & 0xF0); /* sending upper nibble
*/
       LCD_Port &= ~ (1<<RS);</pre>
                                                   /* RS=0, command reg. */
       LCD_Port |= (1<<EN);
                                                  /* Enable pulse */
       _delay_us(1);
       LCD_Port &= \sim (1<<EN);
       _delay_us(200);
       LCD_Port = (LCD_Port & 0x0F) | (cmnd << 4); /* sending lower nibble */
       LCD_Port |= (1<<EN);</pre>
       _delay_us(1);
       LCD_Port &= \sim (1<<EN);
       _delay_ms(2);
}
```

```
void LCD_Char( unsigned char data )
{
       LCD Port = (LCD_Port & 0x0F) | (data & 0xF0); /* sending upper nibble
*/
       LCD_Port |= (1<<RS);</pre>
                                                   /* RS=1, data reg. */
       LCD Port |= (1<<EN);</pre>
       _delay_us(1);
       LCD_Port &= \sim (1<<EN);
       _delay_us(200);
       LCD_Port = (LCD_Port & 0x0F) | (data << 4); /* sending lower nibble */</pre>
       LCD_Port |= (1<<EN);</pre>
       _delay_us(1);
       LCD_Port \&= \sim (1 << EN);
       _delay_ms(2);
}
void LCD_Init (void) /* LCD Initialize function */
       LCD_Dir = 0b11111110; /* Make LCD command port direction as o/p */
       _delay_ms(20);
                            /* LCD Power ON delay always >15ms */
       LCD_Command(0x33);
       LCD_Command(0x32);  /* send for 4 bit initialization of LCD */
       LCD_Command(0x28); /* Use 2 line and initialize 5*7 matrix in (4-bit
mode)*/
       LCD_Command(0x0c); /* Display on cursor off*/
       LCD_Command(0x06); /* Increment cursor (shift cursor to right)*/
       LCD_Command(0x01); /* Clear display screen*/
       _delay_ms(2);
       LCD_Command (0x80); /* Cursor 1st row 0th position */
}
void LCD_String (char *str) /* Send string to LCD function */
       for(i=0;str[i]!=0;i++)/* Send each char of string till the NULL */
       {
              LCD_Char (str[i]);
       }
```

```
}
void LCD_String_xy (char row, char pos, char *str) /* Send string to LCD with
xy position */
       if (row == 0 && pos<16)</pre>
       LCD Command((pos & 0x0F)|0x80); /* Command of first row and
required position<16 */</pre>
       else if (row == 1 && pos<16)</pre>
       LCD_Command((pos & 0x0F)|0xC0); /* Command of first row and
required position<16 */</pre>
       LCD_String(str);
                                            /* Call LCD string function */
}
void LCD_Clear()
                                            /* Clear display */
       LCD_Command (0x01);
       _delay_ms(2);
       LCD_Command (0x80);
                                            /* Cursor 1st row 0th position */
}
int main()
       TCNT0 = 0;
       OCR0 = 255;
       //ctc
       TCCR0 |=(1<<CS02)|(0<<CS01)|(0<<CS00)|(1<<WGM01);
       sei();
       DDRB = 0b11111111;
       LCD_Init();
       while(1){}
       return 0;
}
ISR(TIMER0_COMP_vect)
    overflowCounter++;
       if(overflowCounter == 2){
```

```
if(PORTB & (1 << PB3)){
          PORTB &= ~(1 << PB3);
}else{
          PORTB |= (1 << PB3);
}
          overflowCounter = 0;
}</pre>
```

چالش ها:

طبق شکل دستور کار، پایه RW که در LCD است باید به PA2 وصل شود که در این صورت کار LCD کار نمی کند. با جستجو مشخص شد که این پایه باید به GND وصل شود.

