SAFETY INSPECTION REPORT

Plant: Unit 4 Pump House

Inspector: R. Sharma

Date: 12 October 2026

Findings:

1. Pump P-102 shows oil leakage near the seal.

2. Pressure gauge G-7 reads 12 bar, limit is 10 bar.

3. Fire extinguisher at gate B is expired.

Recommendation:

Shut down pump P-102 for repair within 48 hours.

Replace gauge G-7 and the expired extinguisher.

Approval status: PENDING MANAGER SIGNATURE