TECHNICAL EVALUATION — SIMPLECLEAN WASHING MACHINE

1. Evaluation output

Field	Value
Report	washing_machine_STUESO0520024332206LM.pdf (83 pages)
Standards	IEC 60335-1:2010 (Part 1); IEC 60335-2-7:2012 (Part 2 2-7)
Created	2026-11-01 12:27 UTC

2. Report identity

Field	Value
Report number	STUESO0520024332206LM
Laboratory	Guangzhou STU Hengchuang Testing Service Co. Ltd
Report date	10 April 2026 on cover; 17 April 2026 on issue page
Product declared	Washing machine, SIMPLECLEAN
Declared model	EC/27FW
Standards claimed	US IEC 60335-1:2010; US IEC 60335-2-7:2012
Standards evaluated	US IEC 60335-1:2010; US IEC 60335-2-7:2012, as supplied

3. Summary

Field	Value
Final verdict	REJECT — INSUFFICIENT TECHNICAL EVIDENCE
Reason	Objective failure established by code: Heating table: Internal wire 61.9 K vs 35 K limit. The recorded internal-wire temperature rise of 61.9 K exceeds the report's own 35 K limit. Conflicting product ratings and the photograph also prevent reliable attribution of the results to the declared model.
Recommended action	Resolve the sample identity and recorded failure, complete the applicable tests and issue an authenticated replacement report before certification proceeds.
Conclusion	The report does not establish compliance of model EC/27FW with the supplied general and washing-machine particular standards. In addition to the recorded heating failure, substantial washing-machine-specific evidence is absent or unsupported, including moisture, mechanical-hazard, interlock and abnormal-operation assessments.
Findings	31 total — Critical 4, High 26, Medium 1, Low 0

4. Findings

Priority	Clause	Normative requirement	Finding reason	Required action	Pages	Evidence
Critical	10.1	Power input is assessed against the appliance's rated power input.	The declared rating is 240 V, 400 W, but the power-input table uses a 2,500 W rated basis and records 2,580 W. The photograph also shows a label reading 380 V, three-phase, so attribution of the results to EC/27FW is not established.	Establish the identity and rating of the tested sample and replace the report with traceable results for the declared model.	PDF pp.2,77,83	Report: verified p.77 Standard: verified in IEC 60335-1:2010 p.38
Critical	10.1	The measured power-input deviation is compared with the permitted deviation from rated input.	For 2,500 W rated and 2,580 W measured, the deviation is +3.2%, not the reported +6.7%, +7.3% or +10.0%. The three rows repeat the same powers.	Recalculate the deviations from verified measurements and record the applicable limit and representative operating period.	PDF p.77	Report: verified p.77 Standard: verified in IEC 60335-1:2010 p.38
Critical	11.8	Temperature rises during the heating test shall not exceed the applicable limits.	The report records an internal-wire rise of 61.9 K against its stated limit of 35 K: an objective failure. The general "not out of tolerance" statement and the N/A table verdict do not resolve it.	Investigate the failure, correct the product or demonstrate an expressly applicable different limit, and repeat the relevant assessment.	PDF pp.13,77	Report: verified p.77 Standard: verified in IEC 60335-1:2010 p.41
Critical	—	The supplied standards do not specify report-date consistency or identification of appended photographs.	The cover dates the report 10 April 2026, before the stated test end of 17 April, while the issue page gives 17 April; the only photograph is not linked to the declared model.	Obtain an authenticated replacement report with consistent dates and traceable sample photographs.	PDF pp.1–3,83	Report: approximate p.1 Standard: requirement not in supplied standards
High	10.1	A power-input measurement applies where the appliance is marked with rated power input.	Clause 10.1 is marked N/A on page 11 despite the 400 W declaration and a populated table on page 77; the table uses a conflicting rated input.	Assess the 400 W model at its rated voltage and resolve the inconsistent verdict.	PDF pp.2,11,77	Report: verified p.77 Standard: verified in IEC 60335-1:2010 p.38
High	5.7	Unless otherwise specified, tests are performed in a draught-free location at 20 °C ± 5 °C.	The heating table records an ambient temperature of 45 °C, outside the specified range; no applicable alternative condition is identified.	Repeat the heating assessment at the specified ambient temperature and document the conditions.	PDF p.77	Report: NOT FOUND Standard: verified in IEC 60335-1:2010 p.27
High	3.1.9; 11.7	Washing-machine heating tests use the specified load and water conditions and the applicable operating-cycle sequence.	The report does not record the textile load, initial water temperature, programme or cycle and rest-period sequence needed to establish the washing-machine test conditions.	Document the construction and repeat or substantiate the heating test using the applicable washing-machine conditions and sequence.	PDF pp.12, 13,77	Report: no quote given Standard: verified in IEC 60335-2-7:2012 p.15
High	6.2; 7.1; 15.1.1; 15.1.2	Washing machines shall be at least IPX4, and the IP number other than IPX0 shall be marked.	The report passes ingress protection but gives no classification, marks IP identification N/A, and marks the IPX4 positioning provision N/A without an explanation.	Identify and verify the IP classification and marking and document the applicable IPX4 test arrangement and results.	PDF pp.4,16,17	Report: verified p.4 Standard: verified in IEC 60335-2-7:2012 p.14
High	7.12	The washing-machine instructions shall specify the maximum dry-cloth mass in kilograms.	The report's instructions section does not address the required maximum load; that value also determines the normal-operation test load.	Provide the instructions and record the maximum dry-cloth mass and its use in testing.	PDF pp.6,7	Report: no quote given Standard: verified in IEC 60335-2-7:2012 p.15
High	7.12; 7.12.5	Safe-use instructions, the specified supervision statements and the type Y supply-cord replacement instruction are required.	Type Y attachment is declared, but the report does not address its cord-replacement instruction or the general safety and child-supervision statements.	Examine the supplied instructions and document conformity with the applicable safety and type Y wording.	PDF pp.3,6,7	Report: no quote given Standard: verified in IEC 60335-1:2010 p.34

Priority	Clause	Normative requirement	Finding reason	Required action	Pages	Evidence
High	15.2	Washing machines are tested for spillage, including the prescribed top-surface solution application and, as applicable, overflow treatment.	A pass is recorded against the general spillage wording, but the report gives no washing-machine-specific procedure, solution quantities, overflow conditions or post-test observations.	Perform or substantiate the particular-part spillage test and record its conditions and results.	PDF p.18	Report: verified p.18 Standard: verified in IEC 60335-2-7:2012 p.17
High	15.101; 5.3	The foaming test is performed immediately after 15.2 and before the humidity test, unless the applicable electrolyser provisions replace it.	No foaming test or associated sequence is reported, and the appliance is not described sufficiently to establish an Annex CC alternative.	Identify whether Annex CC applies and document the applicable foaming test, sequence and electric-strength result.	PDF p.18	Report: no quote given Standard: verified in IEC 60335-2-7:2012 p.18
High	15.3	Humidity conditioning requires 48 h at specified humidity and a controlled temperature between 20 °C and 30 °C.	The report records 94% relative humidity but no actual cabinet temperature, conditioning temperature or measured duration; the printed preconditioning expression is incomplete.	Provide the humidity-conditioning record, including actual temperatures, duration and subsequent test results.	PDF p.18	Report: no quote given Standard: verified in IEC 60335-1:2010 p.49
High	18.101; 5.2; 5.3; 22.104	Lid or door interlocks must withstand the specified endurance and resistance-to-forcing tests in the required sequence on the same appliance.	An interlock switch appears in the heating table, but the report does not address interlock endurance, forcing, test sequence or sample continuity.	Identify the interlock and document the applicable endurance and forcing tests on the required sample and in the required sequence.	PDF pp.21, 33,77	Report: no quote given Standard: verified in IEC 60335-2-7:2012 p.18
High	19.1; 19.7	Motors are subject to applicable abnormal-operation tests, except motors driving moving parts of an oscillating agitator.	The report treats the appliance as motor-operated but marks the stalled-condition test N/A and leaves its results table empty without identifying the motor or establishing the exception.	Identify each motor and perform or justify exclusion from the applicable stalled-condition tests.	PDF pp.13, 21,23,78	Report: verified p.78 Standard: verified in IEC 60335-2-7:2012 p.19
High	19.10	An applicable series-motor test is performed at 1.3 times rated voltage for 1 min.	The report records 254.4 V and P; for the declared 240 V rating, 1.3 times rated voltage is 312 V.	Repeat the applicable series-motor test at 312 V for 1 min and record the outcome.	PDF p.24	Report: verified p.24 Standard: verified in IEC 60335-1:2010 p.55
High	19.11; 19.11.2	Electronic circuits are evaluated for specified fault conditions unless the stated exemption conditions are met.	The report passes the electronic-circuit provision but marks the circuit fault evaluation N/A without a circuit description or an assessment supporting exemption.	Identify the electronic circuits and document the fault evaluation or a substantiated exemption.	PDF pp.21, 24,25	Report: verified p.24 Standard: verified in IEC 60335-1:2010 p.55
High	19.101; 19.13	For washing machines with a programmer or timer, specified fault conditions are applied and the textile material shall not ignite, char or glow.	The report omits the particular-part fault conditions and textile acceptance criteria; the presence of a programmer or timer is not established.	Identify the controls and document the applicable washing-machine abnormal tests and textile observations.	PDF pp.21–29	Report: no quote given Standard: verified in IEC 60335-2-7:2012 p.20
High	20.1	For the washing-machine stability test, doors and lids are closed and the appliance is empty or filled, whichever is more unfavourable.	The report passes a general-part statement requiring doors open or closed, whichever is more unfavourable, without recording the particular-part configuration.	Document or repeat the stability test with doors and lids closed and the specified loading condition.	PDF p.30	Report: verified p.30 Standard: verified in IEC 60335-2-7:2012 p.21
High	20.101; 20.102; 20.103; 20.104; 20.105	Applicable washing-machine requirements address unbalanced loads, interlocking and drum stopping or locking.	The report contains no particular-part mechanical-hazard assessment; drum type, loading direction, speed and energy are not identified to determine the relevant interlock and stopping tests.	Establish the machine construction and document the applicable unbalanced-load, interlock and stopping tests.	PDF pp.29–31	Report: no quote given Standard: verified in IEC 60335-2-7:2012 p.21
High	21.101; 21.102	Washing-machine lids and doors require adequate mechanical strength, and lids require resistance to distortion.	The report records general mechanical-strength tests but omits the particular lid and door tests; an interlock switch is recorded without identification of its associated closure.	Identify the lid or door and perform and document the applicable strength and distortion tests.	PDF pp.31 –33,77	Report: no quote given Standard: verified in IEC 60335-2-7:2012 p.22

Priority	Clause	Normative requirement	Finding reason	Required action	Pages	Evidence
High	22.6	Electrical insulation must be protected from condensation and leakage, subject to the particular-part ageing-test exception.	The report marks the construction requirement and leakage test N/A without identifying the water-containing construction or documenting an Annex BB ageing exemption.	Assess condensation and leakage paths and document the applicable inspection, test or ageing-test exemption.	PDF p.35	Report: verified p.35 Standard: verified in IEC 60335-2-7:2012 p.23
High	22.101; 22.103; 22.105	Applicable washing-machine construction provisions control opening of doors, hot-water filter compartments and mechanical emergency releases.	These particular-part provisions are absent, and the report does not identify whether the relevant door, filter compartment or release mechanism exists.	Describe these features and assess each applicable construction requirement.	PDF pp.33–45	Report: no quote given Standard: verified in IEC 60335-2-7:2012 p.24
High	24.1.3; 24.1.4	Required switches and applicable programmers and interlocks must meet the specified component endurance requirements.	A switch is listed as tested with the appliance and an interlock switch is recorded, but switch-cycle and washing-machine interlock or programmer endurance evidence is absent.	Identify the components and provide applicable component approvals or endurance-test results.	PDF pp.48–51,77–79	Report: no quote given Standard: verified in IEC 60335-2-7:2012 p.24
High	25.13	Supply-cord inlet openings must permit introduction without damage and have the specified lining or bushing where applicable.	The appliance has a type Y supply cord, yet the inlet-opening requirement is marked N/A without a construction-based explanation.	Inspect and document the cord inlet and any required lining or bushing.	PDF pp.3,55,78	Report: verified p.55 Standard: verified in IEC 60335-1:2010 p.82
High	27.3	For appliances with supply cords, current-carrying conductors must become taut before the earthing conductor if the cord slips.	The report declares a class I appliance with a type Y supply cord but marks this check N/A without justification.	Inspect the conductor arrangement and document the protective-earthing slack check.	PDF pp.3,54,64	Report: verified p.64 Standard: verified in IEC 60335-1:2010 p.90
High	28.2	Electrical and earthing connections must maintain contact pressure despite applicable insulating-material shrinkage or distortion.	The report marks the requirement N/A even though it records electrical and earthing connections; no construction-based exemption is documented.	Inspect the electrical and earthing connections and document conformity or the applicable exemption.	PDF pp.63, 64,66	Report: verified p.66 Standard: approximate in IEC 60335-1:2010 p.92
High	29.2; 29.2.1; 29.2.3; 29.2.4	Creepage distances depend on working voltage, material group and pollution degree, with the particular washing-machine provisions applied.	The report reproduces the general pollution-degree rule and gives pass verdicts but no identifiable measured creepage paths or CTI evidence; functional creepage is marked N/A in the appended table.	Identify each insulation path, its measured distance, working voltage, CTI and applicable pollution degree or justified exception.	PDF pp.70, 71,79–82	Report: verified p.79 Standard: verified in IEC 60335-2-7:2012 p.25
High	30.1	Relevant non-metallic parts are checked for heat resistance by the specified ball-pressure test.	Clause 30.1 is marked P, but the appended ball-pressure table is N/A and contains no parts, test temperatures or impressions.	Provide the ball-pressure results for the relevant parts or document a valid exclusion for each.	PDF pp.72,82	Report: verified p.82 Standard: verified in IEC 60335-1:2010 p.102
High	30.2.3.1; 30.2.3.2	Where 30.2.3 applies, relevant non-metallic parts supporting or near connections are assessed at the specified glow-wire severities or by permitted alternatives.	The report passes the 850 °C and 750/650 °C provisions, but its only recorded glow-wire result is for the switch enclosure at 550 °C; connection current, exemption and material evidence are not supplied.	Document each relevant part and connection current and provide the required test results or qualifying material evidence.	PDF pp.74, 75,82	Report: verified p.82 Standard: verified in IEC 60335-1:2010 p.104
Medium	7.13; 7.14; 7.15	Required instructions must use an official language of the country of sale, and required markings must be legible, durable and on a main part.	Language and main-part marking are marked N/A; the marking entry concerns a hot-surface symbol rather than the required durability check.	Identify the destination and document the language, location, legibility and durability checks for required markings and instructions.	PDF p.9	Report: verified p.9 Standard: verified in IEC 60335-1:2010 p.35