TECHNICAL EVALUATION REPORT

SUBMERSIBLE PUMP

Evaluation reference	078F36CF — 01 November 2026
Test report evaluated	EN201222034S — EMTEK(NINGBO) CO., LTD. — 28 December 2025
Report file	submersible_pump_EN201222034S.pdf (89 pages)
Product declared	Submersible pump
Standards claimed	IEC 60335-1:2010+A1:2013+A2:2016; IEC 60335-2-41:2025 on page 2; IEC 60335-2-41:2012 in the conclusion on page 3
Standards evaluated	IEC 60335-1:2010 (Part 1); IEC 60335-2-41:2021 (Part 2 2-41)

FINAL VERDICT

REPORT CORRECTION / REPLACEMENT REQUIRED — PRODUCT COMPLIANCE NOT DETERMINED — CERTIFICATION HOLD

The tested model, ratings and recorded test voltages do not consistently match the declared product. Essential immersion, earthing, cord and heat-and-fire evidence is also missing or inadequately attributable.

Prepared by	Reviewed and approved by	Date
Complify Evaluation Engine	Name / signature: _____	01.11.2026

1. Summary

Item	Detail
Report	EN201222034S | EMTEK(NINGBO) CO., LTD. | 28 December 2025
Product declared	Submersible pump
Standards claimed	IEC 60335-1:2010+A1:2013+A2:2016; IEC 60335-2-41:2025 on page 2; IEC 60335-2-41:2012 in the conclusion on page 3
Standards evaluated	IEC 60335-1:2010; IEC 60335-2-41:2012 as endorsed in EN IEC 60335-2-41:2021
Final verdict	REPORT CORRECTION / REPLACEMENT REQUIRED — PRODUCT COMPLIANCE NOT DETERMINED — CERTIFICATION HOLD
Reason	The tested model, ratings and recorded test voltages do not consistently match the declared product. Essential immersion, earthing, cord and heat-and-fire evidence is also missing or inadequately attributable.
Findings	Critical 6, High 15, Medium 0, Low 0
Conclusion	The report does not demonstrate compliance of SPC55068 against the supplied IEC 60335-1:2010 and IEC 60335-2-41:2012 requirements. No measured product failure is established by the supplied records; a replacement, traceable assessment and the missing claimed standard editions or amendments are required before a compliance decision can be made.

2. Findings

'(code)' = the values in this row were also checked by code against the report.

Severity	Clause	Finding	Reason	Required action	Pages
Critical	5.1; 7.1	The declared model is SPC55068, but the test summary identifies the fully tested model as 4TSC4.0-96-110/1000; the photograph depicts a 750 W pump, while the declared rating is 550 W.	Type-test results must be attributable to the appliance under evaluation; no relationship between the models or the pictured pump is established.	Provide a replacement report identifying the tested sample and substantiating its relationship to SPC55068.	PDF pp.1,2,3,88
Critical	7.1 (code)	Inconsistent: The declared rating is 220–240 V, 50 Hz, 550 W, but clause 7.1 records 96 V and the particulars state DC.	The required voltage marking and supply characteristics cannot be verified against contradictory records.	Reconcile the actual nameplate, supply type and tested rating in a replacement report.	PDF pp.2,3,4,6,7
Critical	10.1 (code)	Inconsistent: The declared rated power is 550 W, but the power-input table uses 1,000 W at 72 V and records 995.2 W.	Clause 10.1 requires measurement against the appliance's rated power at rated voltage and normal operation; the recorded basis does not establish compliance for the declared rating.	Provide power-input measurements for the identified 550 W sample at the applicable rated-voltage conditions.	PDF pp.2,3,13,79
Critical	5.8.1; 11.5; 11.7	The heating test records 76.3 V, while the declared appliance is rated 220–240 V, 50 Hz; the actual liquid test temperature is not recorded.	Heating must be assessed at the applicable supply conditions and with liquid maintained at the temperature marked on the pump.	Provide heating results and test conditions attributable to the declared sample and its marked liquid temperature.	PDF pp.2,14,79
Critical	19.7; 19.101	The locked-rotor table records 116.6 V DC and 106.3 °C against a stated 240 °C limit; the dry-running test is marked P without its actual test voltage or head.	These tests require operation at rated voltage, and the recorded DC locked-rotor condition does not match the declared 220–240 V, 50 Hz rating.	Provide traceable abnormal-operation records for the declared sample at the applicable rated supply.	PDF pp.2,20,25,81
Critical	5.1	The specification cites IEC 60335-2-41:2025, while the conclusion cites the 2012 edition; the supplied Part 1 does not include the claimed 2013 and 2016 amendments.	The claimed assessment basis is inconsistent and the unavailable editions and amendments cannot be verified against the supplied standards.	Confirm the intended standards and provide the cited editions and amendments with a corrected assessment.	PDF pp.2,3
High	13.2; 16.2	Both leakage tests record 76.3 V and 0.05 mA; their stated limits are 0.35 mA peak and 0.25 mA, respectively, although the appliance is declared class I.	The tests require the applicable voltage and class-dependent leakage assessment; the recorded voltage does not correspond to the declared 220–240 V rating.	Provide leakage-current results at the applicable voltage using the correct class-I assessment.	PDF pp.2,4,15, 18,79,80
High	7.1	The 550 W submersible pump's maximum operating depth is recorded as N/A, and the marking-plate copy does not show a maximum liquid temperature.	Part 2 requires a maximum operating depth in metres for submersible pumps over 50 W and a maximum liquid temperature of at least 35 °C.	Provide the verified appliance markings and correct the clause verdicts.	PDF pp.3,4,7
High	7.12.1	The maximum total head is marked P with "See marking detail," but no value in metres appears on the supplied marking copy or in the report.	Installation instructions for pumps over 50 W must state the maximum total head.	Provide the applicable installation instructions and record the maximum total head.	PDF pp.3,10
High	15.1.2	The report marks a 24 h immersion and a 1.3-times pressure condition P, but gives no operating depth or actual pressure and refers to 5 m rather than 15 m.	The supplied Part 2 specifies pressure based on operating depth, including 1.3 times the pressure at 15 m if higher, and requires specified water and pump temperatures.	Provide the actual immersion pressure, depth and temperature records and reassess them against Part 2.	PDF pp.4,16,17
High	24.1.3	The photograph shows a float-like device, but level-switch testing is N/A and no switch is identified in the component list.	If the device is a level switch, Part 2 requires 50,000 operating cycles.	Identify the pictured device and provide the applicable level-switch evaluation.	PDF pp.38,82,88
High	24.1.4; 19.7	A self-resetting thermal cut-out is identified, but automatic-control and thermal-motor-protector evaluations are marked N/A.	Applicable control cycling or Annex D testing depends on the device's function and whether it is necessary for compliance; that determination is not recorded.	Identify the protective device and document its compliance evidence or justify the exclusions.	PDF pp.4,38,62
High	24.5; 19.7	The report marks auxiliary-winding capacitor checks P, but the particulars do not identify a motor capacitor, the component list contains none, and capacitor fault tests are N/A.	Where such a capacitor is fitted, its ratings and applicable locked-rotor fault conditions must be assessed.	Clarify whether a capacitor is fitted and provide the applicable component and fault-test evidence.	PDF pp.4,20,40,82

Severity	Clause	Finding	Reason	Required action	Pages
High	25.1; 25.3	The general supply-cord-and-plug entry is P, but the specific class-I submersible-pump plug and flexible-cord entries are N/A; the plug box in the particulars is unchecked.	Part 2 requires a non-class-III submersible pump to have a supply cord fitted with a plug.	Verify the supplied connection and correct the applicable entries.	PDF pp.4,40,41
High	25.7; 25.8	Outdoor use is indicated, but cord type, conductor cross-section and cord length are not recorded and the applicable entries are N/A.	Part 2 specifies cord construction and, for outdoor submersible pumps, a length of at least 10 m or 3 m beyond marked operating depth, whichever is greater; Part 1 specifies minimum conductor area.	Identify and measure the supplied cord and assess it against the applicable requirements.	PDF pp.4,41,42
High	5.101; 25.14	Both portable and fixed classifications are unselected; testing as a portable pump and cord flexing are marked N/A.	Pumps are tested as portable unless fixed, and portable pumps other than the specified exceptions undergo cord-flexing testing.	Establish the pump classification and provide the applicable flexing-test evidence.	PDF pp.4,6,43
High	25.10; 27.3; 27.5	The class-I cord earthing-core and earthing-conductor arrangement are marked N/A; earth continuity is marked P without a measured resistance or test current.	A class-I supply cord requires a green/yellow protective conductor, and earth continuity must be tested with resistance not exceeding 0.1 Ω under the specified conditions.	Provide protective-conductor inspection and earth-continuity test records.	PDF pp.4,43,49
High	29.1; 29.2	The spacing assessment uses a 500 V rated impulse voltage and a working-voltage row of ≤50 V, with basic clearance and creepage reported as >2.0 mm; the declared rating is 220–240 V and pollution degree 3 is recorded.	For category II, Part 1 derives a 2,500 V rated impulse voltage for a 220–240 V rating; creepage depends on the applicable working voltage, pollution degree and material group.	Reassess and document each relevant insulation path using the verified rating, working voltage and material group.	PDF pp.2,54,68,83
High	29.3; 25.13	The report marks the inlet bushing as supplementary insulation and claims compliance by measurement, but gives no insulation thickness and marks the individual assessment routes N/A.	Supplementary insulation must be assessed by an applicable route under 29.3.	Provide the bushing's measured thickness or evidence for another permitted assessment route.	PDF pp.43,54,55
High	30.1; 30.2	Heat and fire resistance are marked N/A and the associated results table is empty, despite an insulating bushing being listed.	Applicable non-metallic parts require heat and fire assessment; Part 2 specifies the applicable fire-test route for pumps.	Identify the relevant parts and provide test or qualifying material evidence for the applicable route.	PDF pp.55–58,82,87
High	29.2	The footer of the final creepage-table page bears report number EN200622010S rather than EN201222034S.	The differing identifier prevents reliable attribution of that page to the report under evaluation.	Replace or authenticate the affected page in a controlled report.	PDF pp.2,86