TECHNICAL EVALUATION REPORT

SUBMERSIBLE PUMP

Evaluation reference	B258AA7A — 01 November 2026
Test report evaluated	EN201222034S — EMTEK(NINGBO) CO., LTD. — Dec 28, 2025
Report file	submersible_pump_EN201222034S.pdf (89 pages)
Product declared	Submersible pump
Standards claimed	IEC 60335-1:2010+A1:2013+A2:2016; IEC 60335-2-41:2025 on page 2; IEC 60335-2-41:2012 on page 3
Standards evaluated	IEC 60335-1:2010 (Part 1); IEC 60335-2-41:2021 (Part 2 2-41)

FINAL VERDICT

REPORT CORRECTION / REPLACEMENT REQUIRED — PRODUCT COMPLIANCE NOT DETERMINED — CERTIFICATION HOLD

The tested model, electrical ratings and test conditions cannot be reliably linked to the declared pump. Applicable safety evidence is also missing or marked N/A without a supported basis.

Prepared by	Reviewed and approved by	Date
Complify Evaluation Engine	Name / signature: _____	01.11.2026

1. Summary

Item	Detail
Report	EN201222034S | EMTEK(NINGBO) CO., LTD. | Dec 28, 2025
Product declared	Submersible pump
Standards claimed	IEC 60335-1:2010+A1:2013+A2:2016; IEC 60335-2-41:2025 on page 2; IEC 60335-2-41:2012 on page 3
Standards evaluated	US IEC 60335-1:2010 and IEC 60335-2-41:2012 as reproduced in ILNAS-EN IEC 60335-2-41:2021
Final verdict	REPORT CORRECTION / REPLACEMENT REQUIRED — PRODUCT COMPLIANCE NOT DETERMINED — CERTIFICATION HOLD
Reason	The tested model, electrical ratings and test conditions cannot be reliably linked to the declared pump. Applicable safety evidence is also missing or marked N/A without a supported basis.
Findings	Critical 5, High 18, Medium 1, Low 0
Evidence check	Report quotes found 10/24; standard quotes found 21/24; not found (needs review) 14
Conclusion	The report does not demonstrate compliance of SPC55068 with the supplied 2010 general part and 2012 pump particular part. An authenticated replacement report, supported by traceable sample identification, correct ratings, applicable test results and the relevant claimed standards and amendments, is required before a certification decision.

2. Findings

'(code)' = the values in this row were also checked by code against the report. Evidence = the AI's verbatim quotes searched by code in the report and standard PDFs; NOT FOUND means the row needs human review.

Severity	Clause	Finding	Reason	Required action	Pages	Evidence
Critical	5.2	The declared model is SPC55068, but the summary states that full tests were performed on model 4TSC4.0-96-110/1000; no relationship between the models is established.	The test evidence cannot be attributed reliably to the declared model.	Provide a replacement report identifying the tested sample and establishing its relationship to SPC55068.	PDF pp.1–3	Report: NOT FOUND Standard: verified in IEC 60335-1:2010 p.26
Critical	7.1 (code)	The declared rating is 220–240 V, but the clause 7.1 entry records 96 V.	The rated-voltage record is inconsistent and cannot establish the marking or test basis.	Reconcile the rated voltage with the actual sample marking and test records.	PDF pp.2–3,6	Report: verified p.6 Standard: verified in IEC 60335-1:2010 p.29
Critical	10.1 (code)	The declared power is 550 W, but the test table uses 1,000 W as the rated basis and records 995.2 W at 72 V.	The recorded power-input test does not demonstrate compliance for the declared rating.	Provide a power-input assessment for the identified 550 W model at the applicable rated voltage or voltages.	PDF pp.2–3,13,79	Report: verified p.79 Standard: verified in IEC 60335-1:2010 p.38
Critical	5.8.1; 10.1; 11.5; 13.1; 16.2; 19.7	The particulars state DC, while the declared rating is 220–240 V, 50 Hz; heating and leakage tables use 76.3 V, and locked-rotor testing uses 116.6 V DC.	The recorded supply and voltages do not establish that the declared appliance was tested under the applicable rated-supply conditions.	Identify the supply and repeat or substantiate the affected tests at the applicable rated conditions.	PDF pp.2–4, 79–81	Report: verified p.81 Standard: verified in IEC 60335-1:2010 p.54
Critical	5.2; 10.1	The photograph attachment depicts a pump marked 750 W and 220–240 V, 50 Hz, rather than the declared 550 W; it is not identified as the tested sample.	The photograph adds a further unresolved conflict in sample and rating traceability.	Replace or identify the photograph and reconcile it with the tested sample and ratings.	PDF pp.2–3,88	Report: verified p.88 Standard: verified in IEC 60335-1:2010 p.28
High	5.101; 25.14	The report marks testing as a portable pump and the cord-flexing test N/A; neither fixed status nor the basis for excluding the test is established.	Pumps are tested as portable unless fixed; portable pumps other than the specified exceptions receive the flexing test.	Establish the pump classification and provide the applicable cord-flexing test results.	PDF pp.4,6,43	Report: NOT FOUND Standard: verified in IEC 60335-2-41:2021 p.13
High	7.1; 15.1.2	The 550 W submersible pump has maximum operating depth recorded as N/A, and the marking copy gives no depth; the immersion test records no actual pressure or depth.	The depth marking is required and determines the specified immersion-test pressure.	Provide the marked maximum operating depth and the corresponding immersion pressure and results.	PDF pp.3–4,7,17	Report: NOT FOUND Standard: verified in IEC 60335-2-41:2021 p.14
High	15.1.2	The report refers to a 5 m alternative under the 1.3-times pressure provision; the supplied particular standard specifies 15 m if higher.	The stated test basis differs from the supplied requirement; actual pressure is not recorded.	Establish the applicable depth and document the test pressure using the supplied standard's 15 m provision where applicable.	PDF p.17	Report: verified p.17 Standard: verified in IEC 60335-2-41:2021 p.16
High	7.1; 5.7; 11.7	The marking copy contains no maximum liquid temperature; the summary states only "<45□", and the heating record does not give the liquid temperature.	A marked maximum of at least 35 °C is required and is the basis for liquid-temperature test conditions.	Provide the actual temperature marking and the measured liquid temperatures used in testing.	PDF pp.3,6–7,14,79	Report: NOT FOUND Standard: verified in IEC 60335-2-41:2021 p.14
High	7.1; 7.12.1	The report refers to marking details for minimum and maximum total head, but the reproduced marking contains neither value and no installation instructions are supplied.	For a pump exceeding 50 W, maximum total head is required in the installation instructions; minimum total head is required on the pump if greater than zero.	Provide the applicable head values and the corresponding marking and installation instructions.	PDF pp.3,7,10	Report: NOT FOUND Standard: verified in IEC 60335-2-41:2021 p.14

Severity	Clause	Finding	Reason	Required action	Pages	Evidence
High	3.1.9; 10.1; 11.7; 19.101	The report records pass verdicts but does not identify the inlet pressure, operating head or highest-power condition used for normal-operation testing; actual head values for the dry-running test are absent.	Normal operation requires the specified inlet condition and a discharge head producing the highest power input.	Provide the hydraulic test conditions and measured head values for the relevant tests.	PDF pp.13–14,25,79	Report: NOT FOUND Standard: verified in IEC 60335-2-41:2021 p.12
High	19.7; 19.13	Locked-rotor winding temperature is recorded as 106.3 °C against 240 °C, but the test duration is not stated; the abnormal-temperature table identifies only locked-rotor conditions.	The applicable duration and winding limit depend on the appliance and protection conditions; the dry-running test also requires assessment against clause 19 criteria.	Provide the locked-rotor duration, protection behaviour and complete clause 19.101 results.	PDF pp.24–25,81–82	Report: verified p.81 Standard: verified in IEC 60335-1:2010 p.54
High	19.7; 24.5	Capacitor marking and voltage checks are passed, while the locked-rotor capacitor open- and short-circuit entries are N/A without an explanation or capacitor classification.	Motors with auxiliary-winding capacitors require the specified fault tests unless the stated exception applies.	Identify the motor capacitor arrangement and provide the applicable fault-test results or justification.	PDF pp.20,40	Report: NOT FOUND Standard: verified in IEC 60335-1:2010 p.54
High	24.1.4	The report image identifies a self-resetting thermal cut-out, but the automatic-control and thermal-motor-protector assessments are marked N/A and the component is not identified in the critical-components table.	The control requires assessment; Annex D applies if a thermal motor protector is necessary for compliance.	Identify the cut-out and document its applicable component and protector assessment.	PDF pp.4,38,62,82	Report: NOT FOUND Standard: verified in IEC 60335-1:2010 p.77
High	24.1.3	The photograph shows a component resembling a float switch, but level-switch testing is marked N/A and the component is not identified.	A level switch, if fitted, is subject to 50,000 operating cycles.	Identify the photographed component and provide the level-switch assessment if applicable.	PDF pp.38,88	Report: NOT FOUND Standard: NOT FOUND
High	25.1; 25.3	The class I submersible-pump-specific cord and plug entries are N/A, although the general plug entry is passed; the particulars image does not select a fitted plug.	The particular standard requires a flexible supply cord fitted with a plug for submersible pumps other than class III.	Document the actual supply connection and plug fitted to the tested sample.	PDF pp.4,40–41	Report: NOT FOUND Standard: verified in IEC 60335-2-41:2021 p.19
High	25.7; 25.8	Outdoor use is selected in the particulars image, but cord type, cross-sectional area and length are not recorded; the cord-length entries are N/A.	The supplied standards specify cord construction and conductor area, and an outdoor submersible pump has a minimum cord-length requirement.	Identify and assess the cord type, conductor area and length against the applicable requirements.	PDF pp.4,41–42,82	Report: NOT FOUND Standard: verified in IEC 60335-2-41:2021 p.19
High	25.10; 27.3; 27.5	For the stated class I pump with a supply cord, the green/yellow core and conductor slack entries are N/A; earth-continuity resistance and test current are not recorded.	Protective earthing and the specified continuity test are safety requirements for the applicable construction.	Provide the protective-conductor inspection and measured earth-continuity test conditions and results.	PDF pp.4,43,48–49	Report: NOT FOUND Standard: verified in IEC 60335-1:2010 p.91
High	29.1; 29.2	The spacing table assesses basic clearance using 500 V impulse and basic creepage at ≤50 V, while the declared rating is 220–240 V; the report also identifies pollution degree 3.	The stated voltage basis is inconsistent with the declared appliance rating, and the actual spacing locations and material group are not established.	Reassess and record the applicable insulation distances using the verified rated and working voltages, pollution degree and material group.	PDF pp.2,54,83–85	Report: verified p.83 Standard: verified in IEC 60335-1:2010 p.99
High	29.3; 25.13	Supplementary-insulation compliance for the inlet bushing is passed, and clause 29.3 is passed by measurement, but the thickness entries are N/A and no measurement is given.	The selected assessment route requires the applicable insulation thickness to be verified.	Provide the bushing insulation thickness and its applicable assessment.	PDF pp.43,54–55	Report: approximate p.54 Standard: verified in IEC 60335-1:2010 p.101
High	30.1	Resistance to heat, including the ball-pressure assessment of relevant non-metallic parts, is marked N/A without justification; an insulating bushing is listed.	Relevant external parts, live-part supports and qualifying insulation require heat resistance assessment.	Identify the relevant parts and provide their heat-resistance assessment or a documented exclusion.	PDF pp.55–56,82,87	Report: NOT FOUND Standard: verified in IEC 60335-1:2010 p.102

Severity	Clause	Finding	Reason	Required action	Pages	Evidence
High	30.2; 30.2.1; 30.2.3	The entire fire-resistance assessment is N/A and its result table is blank; neither the metal-enclosure/RCD conditions nor an alternative assessment is demonstrated.	The particular part selects clause 30.2.1 for qualifying submersible pumps and clause 30.2.3 for other pumps.	Establish the applicable fire-test route and provide the required part-by-part evidence.	PDF pp.56–59,87	Report: NOT FOUND Standard: verified in IEC 60335-2-41:2021 p.20
High	—	The claimed particular-part edition differs between the test specification and compliance statement; the claimed 2025 edition and Part 1 amendments are not supplied. The supplied European foreword also calls for A11:2021, which is absent.	Compliance with the unsupplied claimed editions and amendments cannot be evaluated.	Provide the claimed standards and amendments and issue a consistent statement of the assessment basis.	PDF pp.2–3	Report: verified p.2 Standard: requirement not in supplied standards
Medium	—	Page 86 bears report number EN200622010S rather than EN201222034S.	The differing identifier undermines traceability of the appended spacing table.	Replace the page with an authenticated page belonging to this report.	PDF pp.2,86	Report: verified p.86 Standard: requirement not in supplied standards