# TECHNICAL EVALUATION — WASHING MACHINE

## 1. Evaluation output

| Field | Value |
|---|---|
| **Report** | 1.washing machine.pdf (83 pages) |
| **Standards** | IEC 60335-1:2010 (Part 1); IEC 60335-2-7:2012 (Part 2 2-7) |
| **Created** | 2026-11-04 09:31 UTC |

## 2. Report identity

| Field | Value |
|---|---|
| **Report number** | STUESO0520024332206LM |
| **Laboratory** | Guangzhou STU Hengchuang Testing Service Co. Ltd |
| **Report date** | Apr.10.2026; issue date Apr.17.2026 |
| **Product declared** | Washing machine, 240 V, 50 Hz, 400 W, Class I, Type Y attachment |
| **Declared model** | EC/27FW |
| **Standards claimed** | US IEC 60335-1:2010; US IEC 60335-2-7:2012; IEC 60335-1:2010 |
| **Standards evaluated** | Supplied IEC 60335-1:2010 and IEC 60335-2-7:2012 merged requirements |

## 3. Summary

| Field | Value |
|---|---|
| **Final verdict** | REPORT REJECTED — NON-CONFORMITY ESTABLISHED |
| **Reason** | The report records an internal-wire temperature rise of 61.9 K against its own 35 K limit. Product attribution, test conditions and substantial washing-machine-specific evidence are also unresolved. |
| **Recommended action** | Resolve the measured failure and sample identity, complete the applicable assessments and issue a traceable replacement report before certification proceeds. |
| **Conclusion** | The submitted report does not demonstrate compliance with the supplied IEC requirements. Its recorded temperature-limit failure is decisive, while the conflicting power rating, incomplete Part 2 assessments and document-integrity defects independently prevent a reliable compliance decision. |
| **Findings** | 48 total — Critical 3, High 41, Medium 4, Low 0 |

## 4. Findings

| Priority | Clause | Normative requirement | Finding reason | Required action | Pages | Evidence |
|---|---|---|---|---|---|---|
| **Critical** | 10.1 | The measured power input shall be assessed against the rated power input. | The declared rating is 400 W, but the appended table identifies a 2,500 W rating and 2,580 W measurement; attribution to the declared model is unresolved. | Establish sample identity and provide a valid power-input assessment against its marked rating. | PDF pp.1–3,77 | Report: no quote given Standard: NOT FOUND |
| **Critical** | 11.8 | Measured temperature rises shall not exceed the applicable limits. | The heating table records an internal-wire rise of 61.9 K against its own 35 K limit; this is an objective failure despite the inconsistent table verdict and product attribution. | Investigate the failure and retest an identified representative sample after corrective action. | PDF pp.13,77 | Report: no quote given Standard: verified in IEC 60335-1:2010 (Part 1) p.41 |
| **Critical** | 4 | Compliance is established by fulfilling relevant requirements and carrying out relevant tests. | The report includes washing-machine-unrelated instruction and marking text, a displaced clause reference and inconsistent verdicts, casting doubt on template and result attribution. | Replace or correct the report with a traceable washing-machine assessment and verified verdicts. | PDF pp.5–9 | Report: verified p.6 Standard: verified in IEC 60335-1:2010 (Part 1) p.25 |
| **High** | 10.1 | An appliance marked with rated power input shall be assessed against Table 1. | The clause is marked N/A despite the 400 W marking; the contradictory appended table does not establish compliance for that rating. | Measure and assess input at rated voltage under normal operation. | PDF pp.4,11,77 | Report: no quote given Standard: verified in IEC 60335-1:2010 (Part 1) p.38 |
| **High** | 11.1; 11.3; 11.7; 11.8 | Normal heating is assessed over the specified operating cycles with relevant temperature rises monitored. | Heating is marked N/A, while a temperature table and a qualitative pass appear; the applicable cycle, loading, ambient, limits and complete valid results are not established. | Perform and document the complete heating test on the identified appliance. | PDF pp.12–13,77 | Report: verified p.13 Standard: verified in IEC 60335-2-7:2012 (Part 2) p.15 |
| **High** | 5.2 | Relevant tests of 21.101, 21.102 and 22.104 shall use the appliance used for Clause 18 testing. | The report does not establish sample allocation or the required common test specimen. | Identify specimens and document the required test sequence and sample linkage. | PDF p.4 | Report: verified p.4 Standard: verified in IEC 60335-2-7:2012 (Part 2) p.14 |
| **High** | 6.2 | Washing machines shall have at least IPX4 protection. | Classification is passed without an identifiable IP rating or specific IPX4 result. | Record the classification and substantiate it with the applicable ingress test. | PDF pp.4,16 | Report: verified p.4 Standard: verified in IEC 60335-2-7:2012 (Part 2) p.14 |
| **High** | 7.1 | The IP number, other than IPX0, shall be marked on the appliance. | IP marking is marked N/A although the supplied Part 2 requires at least IPX4. | Verify and document the required IP marking on the appliance. | PDF pp.4–5 | Report: verified p.4 Standard: verified in IEC 60335-1:2010 (Part 1) p.29 |
| **High** | 7.1 | Appliances without automatic water-level control require maximum-level marking, and applicable cold-supply appliances require a hot-water caution. | The report does not identify water-level control, heating or supply arrangements sufficiently to assess the Part 2 markings. | Establish applicability and document the required markings or justified exclusions. | PDF pp.4–5 | Report: verified p.4 Standard: verified in IEC 60335-2-7:2012 (Part 2) p.14 |
| **High** | 7.10 | If the off position is indicated only by letters, the word "off" shall be used. | The extracted report contains "OF" and an F verdict in the control-position area, but the attribution and actual marking are unclear. | Clarify the F verdict and verify the actual off-position marking against Part 2. | PDF p.6 | Report: no quote given Standard: verified in IEC 60335-2-7:2012 (Part 2) p.15 |
| **High** | 7.12 | Instructions shall specify the maximum mass of dry cloth in kilograms and the specified safe-use statements. | The instruction assessment passes unrelated text but does not document the dry-cloth mass or the supplied standard's supervision statements. | Submit and assess the actual instructions against 7.12. | PDF pp.6–8 | Report: verified p.6 Standard: verified in IEC 60335-2-7:2012 (Part 2) p.15 |

| Priority | Clause | Normative requirement | Finding reason | Required action | Pages | Evidence |
|---|---|---|---|---|---|---|
| **High** | 7.12.1 | Installation instructions shall address precautions and, where applicable, unobstructed base ventilation openings. | No report row establishes whether base ventilation openings are present or whether the required carpet warning applies. | Inspect the construction and document the applicable installation instructions. | not stated | Report: no quote given Standard: verified in IEC 60335-2-7:2012 (Part 2) p.15 |
| **High** | 7.12.5 | Type Y appliances require the specified damaged-cord replacement instruction. | Type Y attachment is declared, but no 7.12.5 instruction assessment is reported. | Verify and record the required Type Y cord-replacement instruction. | not stated | Report: no quote given Standard: verified in IEC 60335-1:2010 (Part 1) p.34 |
| **High** | 7.12.8; 22.47; 22.48; 24.7 | Water-mains appliances require applicable pressure instructions, pressure and backsiphonage assessment, and compliant detachable hose-sets. | These requirements are marked N/A without establishing whether the washing machine is intended for water-mains connection. | Establish the water connection arrangement and complete the applicable assessments or document the exclusions. | PDF pp.8–9,44–45,52 | Report: verified p.44 Standard: verified in IEC 60335-1:2010 (Part 1) p.72 |
| **High** | 7.14; 7.15 | Required markings shall be durable and located as specified. | The report addresses a hot-surface symbol instead of marking durability and marks the main-part location requirement N/A. | Assess marking durability and location on the actual appliance. | PDF p.9 | Report: verified p.9 Standard: verified in IEC 60335-1:2010 (Part 1) p.35 |
| **High** | 13.1; 13.2; 13.3 | Leakage current and electric strength shall be checked at operating temperature after the specified operating period. | The operating sequence is unsubstantiated, the leakage table has unclear supply and result attribution, and no operating-temperature electric-strength values are identified. | Provide traceable operating-temperature conditions, measurements and electric-strength results. | PDF pp.13–15,77–78 | Report: verified p.77 Standard: verified in IEC 60335-1:2010 (Part 1) p.44 |
| **High** | 14; 29.1 | Applicable clearances shall meet Table 16 or, where permitted, withstand the impulse test. | Clause 14 is N/A and the clearance table gives only broad distances without identifying measured locations, exposure to movement or the basis for excluding impulse tests. | Identify and measure critical clearances and perform any applicable impulse tests. | PDF pp.15, 78–79 | Report: verified p.79 Standard: verified in IEC 60335-1:2010 (Part 1) p.94 |
| **High** | 15.1; 15.1.1; 15.1.2 | The enclosure shall withstand the ingress test appropriate to its classification and subsequent electric-strength assessment. | Generic IP test text is passed, but the selected IP level, test method and configuration are not recorded; the IPX4 configuration is marked N/A. | Perform and document the applicable IPX4 or higher test and subsequent checks. | PDF pp.15–18 | Report: verified p.16 Standard: verified in IEC 60335-1:2010 (Part 1) p.48 |
| **High** | 15.2 | Spillage testing shall include the Part 2 filling or overflow procedure and the specified treatment over the appliance. | A generic spillage statement is passed without the applicable overflow, detergent, top-spillage, control-operation or subsequent inspection details. | Conduct and document the applicable Part 2 spillage procedure and subsequent checks. | PDF p.18 | Report: verified p.18 Standard: verified in IEC 60335-2-7:2012 (Part 2) p.17 |
| **High** | 15.101 | Foaming shall not affect insulation, as verified by the specified cycle and electric-strength test. | The washing-machine foaming test has no report row or result. | Perform and document the foaming test and subsequent electric-strength test. | not stated | Report: no quote given Standard: verified in IEC 60335-2-7:2012 (Part 2) p.18 |
| **High** | 18.101; 18.102 | Door or lid interlocks and applicable braking mechanisms shall withstand their specified endurance cycles. | No endurance assessment is reported; the door or lid construction and any opening during extraction are not established. | Identify the construction and complete the applicable endurance tests. | not stated | Report: no quote given Standard: verified in IEC 60335-2-7:2012 (Part 2) p.18 |
| **High** | 19.7 | Appliances incorporating motors shall undergo the applicable stalled-condition test. | The motor-operated test condition is recorded, yet locked-rotor testing and its results are N/A. | Perform and record the applicable stalled-condition tests for each motor. | PDF pp.13, 23–24,78 | Report: verified p.78 Standard: verified in IEC 60335-1:2010 (Part 1) p.54 |

| Priority | Clause | Normative requirement | Finding reason | Required action | Pages | Evidence |
|---|---|---|---|---|---|---|
| **High** | 19.10 | Applicable series-motor appliances are tested at 1.3 times rated voltage for one minute. | The report passes the series-motor row using 254.4 V, whereas 1.3 × 240 V is 312 V; actual motor type is not established. | Confirm motor type and, if applicable, test at 312 V for one minute. | PDF p.24 | Report: verified p.24<br>Standard: verified in IEC 60335-1:2010 (Part 1) p.55 |
| **High** | 19.11; 19.11.2; 19.11.4 | Applicable electronic circuits require fault evaluation and relevant electronic-disconnection or protective-circuit tests. | Clause 19 passes the presence of electronic-circuit testing, but 19.11 is N/A and no fault evaluation is documented. | Identify the circuits and complete or justify exclusion of each applicable electronic fault and immunity test. | PDF pp.21, 24–28 | Report: verified p.21<br>Standard: verified in IEC 60335-1:2010 (Part 1) p.55 |
| **High** | 19.101; 19.102 | The specified washing-machine faults and, where applicable, hot-water abnormal operation shall be assessed. | Neither Part 2 abnormal-operation clause is reported; the appliance's water and heating arrangements are insufficiently identified. | Establish applicability and perform the relevant Part 2 abnormal tests. | not stated | Report: no quote given<br>Standard: verified in IEC 60335-2-7:2012 (Part 2) p.20 |
| **High** | 19.13 | Abnormal testing shall meet the specified safety criteria, including the Part 2 textile and interlock requirements. | The generic pass does not record textile ignition, charring or glowing, or the applicable post-test interlock checks. | Document the Part 2 abnormal-test observations and post-test checks. | PDF pp.28–29 | Report: verified p.28<br>Standard: verified in IEC 60335-2-7:2012 (Part 2) p.20 |
| **High** | 20.1 | Stability testing uses closed doors and lids and the most unfavourable castor position. | The report repeats the Part 1 open-or-closed condition without identifying the actual door, lid or castor configuration. | Document the stability test using the applicable Part 2 configuration. | PDF pp.29–30 | Report: verified p.29<br>Standard: verified in IEC 60335-2-7:2012 (Part 2) p.21 |
| **High** | 20.102; 20.103; 20.104; 20.105 | Applicable drum machines require unbalanced-load and door or lid interlock safety assessments. | No Part 2 mechanical-hazard rows are reported, and drum type, extraction speed and interlock arrangement are not identified. | Characterize the drum and interlock and complete the applicable mechanical-hazard tests. | not stated | Report: no quote given<br>Standard: verified in IEC 60335-2-7:2012 (Part 2) p.21 |
| **High** | 21.101; 21.101.1; 21.101.2; 21.102 | Lids and doors shall have adequate mechanical strength and applicable lids shall resist distortion. | No Part 2 lid or door strength assessment is reported, and the closure construction is not established. | Identify the closure and perform the applicable strength and distortion tests. | not stated | Report: no quote given<br>Standard: verified in IEC 60335-2-7:2012 (Part 2) p.22 |
| **High** | 22.6; 22.7 | Insulation shall be protected from condensation or leakage, and appliances containing liquid require safeguards against excessive pressure. | Both clauses are N/A without a construction-based explanation for this washing machine. | Inspect the liquid system and assess or justify exclusion of each requirement. | PDF p.35 | Report: verified p.35<br>Standard: verified in IEC 60335-1:2010 (Part 1) p.64 |
| **High** | 22.101; 22.102; 22.103; 22.104; 22.105 | Applicable washing-machine construction shall protect against water discharge, textile contact with heaters and unsafe opening of interlocks. | No Part 2 construction rows establish applicability or compliance for the door, filter, heater and interlock arrangements. | Inspect the construction and perform the applicable Part 2 checks and interlock tests. | not stated | Report: no quote given<br>Standard: verified in IEC 60335-2-7:2012 (Part 2) p.23 |
| **High** | 24.1 | Components shall meet applicable IEC safety requirements and be assessed in their conditions of use. | The component table lists a 220 V plug for the declared 240 V appliance without establishing its suitability at the appliance rating. | Identify the actual plug and demonstrate its suitability for the rated supply. | PDF pp.1–3,78–79 | Report: verified p.78<br>Standard: verified in IEC 60335-1:2010 (Part 1) p.75 |
| **High** | 24.1.3; 24.1.4 | Applicable switches and automatic controls require assessment to their relevant standards and specified operating cycles. | A switch is listed, but no switch-cycle assessment is reported; the presence and rating of a door or lid interlock are also unresolved. | Identify safety-relevant controls and provide their applicable cycle evidence or tests. | not stated | Report: no quote given<br>Standard: verified in IEC 60335-1:2010 (Part 1) p.76 |

| Priority | Clause | Normative requirement | Finding reason | Required action | Pages | Evidence |
|---|---|---|---|---|---|---|
| **High** | 25.1; 25.5; 25.7 | Supply connection, attachment method and cord type shall meet the applicable construction requirements. | No rows assess the means of supply connection, Type Y attachment construction or cord-type suitability. | Inspect and document the applicable supply connection, attachment and cord requirements. | not stated | Report: no quote given Standard: verified in IEC 60335-1:2010 (Part 1) p.80 |
| **High** | 25.13 | Supply-cord inlet openings shall protect the cord and have applicable insulation or bushings. | The inlet requirement is N/A despite the declared Type Y supply cord, with no construction-based explanation. | Inspect the inlet and verify its cord protection and applicable bushing insulation. | PDF p.55 | Report: verified p.55 Standard: verified in IEC 60335-1:2010 (Part 1) p.82 |
| **High** | 26.1 | Appliances require effective external-conductor connections with the specified terminal accessibility. | The general terminal requirement is marked N/A without identifying the actual connection construction. | Inspect external-conductor connections and document terminal accessibility. | PDF p.60 | Report: verified p.60 Standard: verified in IEC 60335-1:2010 (Part 1) p.87 |
| **High** | 27.3 | On corded appliances, current-carrying conductors shall become taut before the earthing conductor if the cord slips. | The corded-appliance requirement is N/A despite the Class I Type Y supply connection. | Inspect and document conductor lengths and routing at the cord anchorage. | PDF p.64 | Report: verified p.64 Standard: verified in IEC 60335-1:2010 (Part 1) p.90 |
| **High** | 27.5 | Earthing resistance shall not exceed 0.1 Ω at the specified test current. | The report records 0.027 Ω but does not identify the applied current, source voltage or tested accessible parts. | Record the test current, source and each assessed earthing path. | PDF pp.64–65 | Report: verified p.64 Standard: verified in IEC 60335-1:2010 (Part 1) p.90 |
| **High** | 28.2; 28.4 | Relevant electrical and earthing connections shall retain contact pressure and be secured against loosening. | Both general connection requirements are N/A without identifying the connections or demonstrating that exclusions apply. | Inspect the electrical and earthing connections and document compliance or justified exclusions. | PDF pp.66–67 | Report: verified p.66 Standard: verified in IEC 60335-1:2010 (Part 1) p.92 |
| **High** | 29.2; 29.2.1; 29.2.3; 29.2.4 | Creepage assessment shall account for working voltage, material group and the Part 2 pollution and CTI requirements. | The report cites the Part 1 pollution-degree default but does not establish the Part 2 exposure exceptions, CTI values or measured creepage locations; the functional table is N/A. | Identify insulation locations, exposure, CTI, working voltages and measured creepage distances. | PDF pp.69–71,79–82 | Report: verified p.69 Standard: verified in IEC 60335-2-7:2012 (Part 2) p.25 |
| **High** | 29.3; 29.3.1; 29.3.2; 29.3.3; 29.3.4 | Supplementary and reinforced insulation shall be verified by an applicable thickness, layer or electrical-strength route. | Clause 29.3 is passed while all listed verification subclauses are N/A; the applicable route and results are not identified. | Identify each insulation system and document its applicable verification route and results. | PDF pp.71–72 | Report: verified p.71 Standard: verified in IEC 60335-1:2010 (Part 1) p.101 |
| **High** | 30.1 | Relevant non-metallic and insulating parts shall withstand the applicable ball-pressure test. | The clause is passed, but the ball-pressure table is N/A and contains no part, temperature or impression result. | Test or substantiate each applicable part and record the results. | PDF pp.72, 82–83 | Report: verified p.82 Standard: verified in IEC 60335-1:2010 (Part 1) p.102 |
| **High** | 30.2.1; 30.2.3.1; 30.2.3.2; 30.2.4 | Applicable non-metallic parts and PCB materials shall meet the specified fire-resistance tests or documented alternatives. | The report passes fire clauses but the appended table identifies only a switch enclosure and does not establish the full part selection, test severity, material alternatives or consequential tests. | Provide a part-by-part fire assessment with test results or valid material evidence. | PDF pp.73–76,82–83 | Report: verified p.82 Standard: verified in IEC 60335-1:2010 (Part 1) p.102 |
| **High** | 4 | Relevant tests are required to support the compliance assessment. | The stated report date, Apr.10.2026, precedes the end of the stated test period, Apr.17.2026; a separate issue date is also Apr.17.2026. | Clarify and correct the report and issue dates with laboratory authorization. | PDF pp.1–3 | Report: verified p.1 Standard: verified in IEC 60335-1:2010 (Part 1) p.25 |

| Priority | Clause | Normative requirement | Finding reason | Required action | Pages | Evidence |
|---|---|---|---|---|---|---|
| **Medium** | 10.1 | The power-input deviation shall be determined from the rated and measured inputs. | The repeated 2,500 W and 2,580 W values give +3.2%, not the reported +6.7%, +7.3% or +10.0%. | Correct the calculations and identify each measurement. | PDF p.77 | Report: no quote given<br>Standard: verified in IEC 60335-1:2010 (Part 1) p.38 |
| **Medium** | 7.13 | Required instructions and text shall be in an official language of the country of sale. | The language requirement is marked N/A and the destination market is not identified. | Identify the market and verify the language of the required text. | PDF p.9 | Report: verified p.9<br>Standard: verified in IEC 60335-1:2010 (Part 1) p.35 |
| **Medium** | 22.41 | Appliances shall not incorporate mercury-containing components other than lamps. | The prohibition is marked N/A without documenting component inspection. | Verify the component construction and record compliance. | PDF p.43 | Report: verified p.43<br>Standard: verified in IEC 60335-1:2010 (Part 1) p.71 |
| **Medium** | 1 | The supplied evaluation basis is the stated IEC Part 1 and Part 2 requirements. | The report claims US IEC editions, but the supplied material does not establish whether US deviations were applied or how they relate to the evaluated IEC texts. | Identify the exact standards and deviations used and reconcile the assessment with the supplied IEC basis. | PDF pp.1–3 | Report: verified p.1<br>Standard: requirement not in supplied standards |