

(a) Task 1: full exterior scan

T line	0.98	0.00	0.79	0.48	0.96	0.99	0.99
T pipe (circle)	0.00	0.04	0.41	0.35	0.06	--	1.00
T pipe (cut)	0.00	0.04	0.12	0.28	0.03	--	0.87
T saddle	0.00	0.02	0.13	0.30	0.04	--	0.90
T rect. tube	0.00	0.03	0.10	0.37	0.07	--	0.63
T swept stiffener	0.77	0.00	0.72	0.45	0.92	--	1.00
corner	0.50	0.00	0.99	0.50	0.65	0.99	1.00
butt square	0.00	0.01	0.59	0.01	0.54	0.97	0.99
butt grooved	0.00	0.00	0.00	0.03	0.00	--	0.00
butt arc	0.00	0.00	0.63	0.00	0.01	--	0.69
lap	0.00	0.03	0.56	0.37	0.84	0.69	0.88
edge	0.00	0.04	0.29	0.34	0.37	0.32	0.90
	M1	M2	M3	M4	M5	M6	M7

(b) single view

0.67	0.31	0.55	0.46	0.02	0.43	0.65
0.00	0.09	0.38	0.36	0.01	--	0.41
0.10	0.10	0.43	0.28	0.03	--	0.56
0.16	0.07	0.57	0.25	0.06	--	0.67
0.38	0.10	0.34	0.37	0.02	--	0.44
0.60	0.12	0.62	0.54	0.00	--	0.61
0.93	0.30	0.76	0.05	0.01	0.18	1.00
0.00	0.04	0.22	0.02	0.63	0.95	0.60
0.00	0.00	0.00	0.00	0.47	--	0.00
0.00	0.26	0.67	0.00	0.73	--	0.99
0.00	0.04	0.56	0.35	0.09	0.26	0.59
0.00	0.34	0.40	0.04	0.24	0.21	0.43
M1	M2	M3	M4	M5	M6	M7

median F1 @ 3 mm