

→ transition - - - → re-identify - - - → unplugged → position out

```

graph LR
    A[range stretch min..max] --> B[invert if set]
    B --> C[drive curve bend -1..1]
    C --> D[CC 0..127 with hysteresis]
    D --> E[USB MIDI and LED]
  
```

